THEOLIGA  THEOLIGA  NEW MEXICO OIL CONSERVATION COMMISSION  FILE  U.S.G.S.  LAND OFFICE  OPERATOR	Supervedes Old G-102 and C-103 Effective 1-1-65  Sa. Indicate Type of Lease State The X  5. State Oil & Gas Lease No.
IND NOT USE THIS FORM FOR PROPERTY TO DRILL ON TO DIEFEN ON PLUG BACK TO A DIFFERENT RESERVOIR.	
OIL X GAS OTHER.	7, Unit Agreement Name
Cities Service Company	R. Farm or Leane Hame
3. Address of Operator	Fort Union
Box 1919 - Midland, Texas 79702	1
	10. I'tald and I'nol, or Wildcat
UNIT LETTER B 660 FEET FROM THE NORTH LINE AND 1980 FEET FROM	11/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1
East LINE SECTION 33 TOWNSHIP 20N BANGE 19E	
15, Elevation (Show whether DF, RT, GR, etc.)	
7321' GR	12. County
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	Mora ()
NOTICE OF INTENTION TO: SUBSEQUENT	
TEMPORABLY ABANDON COMMINCE DRILLING OFNS.	ALTIENG CANING
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT X
OTHER	
the production of the producti	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  T.D. 5832. P.B.T.D. 2250.	
Drilled out to 2348'. Perf. Glorieta with 2 0.46" shots per foot from 2119'-2138'. No gas or show of CO2. Set CIBP @ 2090' with 8 sacks cement on top. New P.B.T.D. 2062'.	
Perf. additional Glorieta with 2 0.46" shots per foot from 1940'-1950', 1970'-1972', 1980'-1990' and 1999'-2004'. 44 hour SITP 42#. Swabbed 325 barrels of water in 9 hours. No gas. Set CIBP @ 1930' with 6 sacks of cement on top. New P.B.T.D. 1902'.	
Perf. additional Glorieta with 2 0.46" shots per foot @ 1871'-1875', Swabbed 2 barrels of water and no gas. Swabbed dry. 14 hour SITP 41#. Swabbed 17 barrels of water with very slight gas show. Acidized perforations 1871'-1875' with 1000 gallons of 7 1/2% MCA. 15 1/2 hour SITP 48#. Swabbed 45 barrels of formation water. Swabbed dry.	
Plugged and abandoned well as follows:  1. Set CIBP @ 1861' with 8 sacks on top.  2. Set 10 sacks of cement in 8 5/8" casing from 10' to surface.  3. Cleaned location.  4. Installed 4" dry hole marker.	
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Region Operations Manager	<u>September 26, 197</u> 8
SENIOR PETROLEUM GEOLOGIST	DATE 12/14/19

CONDITIONS OF APPROVAL, IF ANY: