

H-11-19N-21E - From Frigidice well (above) to Cox Berliar Well No. 1 drilled in 1950 and 1951. O.C.C. hearing on 4/24/51 (Case #271) was forced plugging attempt - not followed by an order. Wagon Mound rancher, Wiggins, had knowledge of operation and accompanied me to location. There were actually two wells drilled here but casing for either could not be found. If casing was set, it is now below ground level. Wells were drilled with cable tools. Locations are very messy. Much steel cable, rig lumber, and other junk remaining. Locations were not leveled. No identification, no bond in effect. CU 8-8-74