

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

IN OFFICE NOV 18 1968

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-6583	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: Dry Hole		7. Unit Agreement Name
2. Name of Operator D. C. Prince, Trustee		8. Farm or Lease Name Cotton-State
3. Address of Operator 1507 Texas Avenue Lubbock, Texas		9. Well No. 1
4. Location of Well UNIT LETTER A 660 FEET FROM THE North LINE AND 624.7 FEET FROM THE East LINE, SECTION 19 TOWNSHIP 16N RANGE 31E NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4470 DF		12. County Quay

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spud 8-18-68

Drill 12-3/4" hole to 200'. Run 200' 8-5/8" casing to TD. Cement w/250 sx cement, circulated to surface.

Drill 7-7/8" hole to 1682'. Attempt to run DST. Packer failed, test tool stuck in hole, unable to recover. Back off drill pipe and test tool 1233'. Lost circ. 794'-804' and below 1233'. Squeeze with 300 sx cement 400' to 1233'.

Propose to plug as follows:

Set bridge basket @ 1233'. 25' cement plug to 1208'. Heavy mud 1208' to 815'. Cement plug 815'-775'. Heavy mud 775' to 215'. Cement plug 215'-185'. Heavy mud 185'-15'. Cement plug 15' - surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. C. Prince, Trustee TITLE Owner DATE Nov. 12, 1968

APPROVED BY J. E. Kapteina TITLE Oil & Gas Inspector DATE 7/27/70

CONDITIONS OF APPROVAL, IF ANY:

State. IV