

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

| | | | |
|-----------------|------------------------|---------------|--------------|
| Name of Company | ABO Petroleum Corp | Contact | Dan Lewis |
| Address | 411 West Main, Artesia | Telephone No. | 575-748-4251 |
| Facility Name | Angle State #1 | Facility Type | Well |

| | | | | | |
|---------------------|--|---------------|--------------------|---------|------------|
| Surface Owner State | | Mineral Owner | ABO Petroleum Corp | API No. | 3002501984 |
|---------------------|--|---------------|--------------------|---------|------------|

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| C | 9 | 17 | 34 | 660 | N | 1980 | W | Lea |

Latitude _____ Longitude _____

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|---|---------|----------------------------|---------|
| Type of Release | Produced Water | Volume of Release | 10 BBLs | Volume Recovered | -0- |
| Source of Release | Flow line leak | Date and Hour of Occurrence | | Date and Hour of Discovery | 1-30-15 |
| Was Immediate Notice Given? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | OCD | | |
| By Whom? | Surface Owner | Date and Hour | 1-30-15 | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Internal corrosion caused a flow line leak.
Flow line was repaired with a clamp.

Describe Area Affected and Cleanup Action Taken.*

Area of leak 100 ft long and 40 ft wide at widest point, excavated top 8 inches to topsoil and removed it. Got down to clean soil at that point. Took sample for testing

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|-----------------|----------------|---|-----------------------------------|
| Signature: | | OIL CONSERVATION DIVISION | |
| Printed Name: | Dan S. Lewis | Hydrologist | |
| Title: | Treasurer | Approved by Environmental Specialist: | |
| E-mail Address: | dan@abopet.com | Approval Date: 02/11/2015 | Expiration Date: 04/11/2015 |
| Date: | 2-2-15 | Conditions of Approval: | Attached <input type="checkbox"/> |
| Phone: | 575-748-4251 | Site samples required. Delineate and remediate area as per NMOCD guides | 1RP-3529 |

* Attach Additional Sheets If Necessary

nTO1504241164

pTO1504241393