

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

4RP-17  
State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

**OPERATOR**       Initial Report       Final Report

Name of Company ARP Production Company, LLC	Contact Randy L. Madison
Address 309 Silver St., Raton, NM 87740	Telephone No. Office 575-445-6706    Cell 575-420-1120
Facility Name E-501 Low Pressure Suction Line	Facility Type: Compressor Station

Surface Owner Vermejo Park Ranch	Mineral Owner APR Production Company, LLC	API No. N/A
----------------------------------	---	-------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	4	31N	19E	N/A	N/A	N/A	N/A	Colfax

Latitude N. 36.98715    Longitude W 104.92115

#### NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: 150 MCF	Volume Recovered: 0
Source of Release: Low pressure suction gas line	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery 4/13/17 @ 1546
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Leonard Lowe	
By Whom? Randy Madison	Date and Hour: 4/13/17 @ 1600	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A 10" suction line with a drip attached to it settled over time. This caused the 1" line coming of the bottom of the drip for draining purposes to bend and crack at the threads. This released 150 MCF of gas. The line and drip were excavated and the 1" line replaced. Settling should not be a factor in the future.

Describe Area Affected and Cleanup Action Taken.\*  
There were not notable affects and no clean up needed as this was natural gas.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:  Printed Name: Randy L. Madison Title: EHS Specialist E-mail Address: rmadison@atlasenergy.com Date: 4/24/17	<b>OIL CONSERVATION DIVISION</b>  Approved by Environmental Specialist:  Hydrologist District IV Approval Date: 26Apr17      Expiration Date: n.a. Conditions of Approval: <b>None</b> Attached <input type="checkbox"/>
Phone: 575-445-6706	

