

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Incident ID	pDHR1919036410
District RP	1RP-5611
Facility ID	fAB1909457353
Application ID	nDHR1919037288

Release Notification

Responsible Party

Responsible Party OCCIDENTAL PERMIAN LTD.	OGRID 2656-M5
Contact Name CHAD DENNIS	Contact Telephone 432-758-8614
Contact email CHAD_DENNIS@OXY.COM	Incident # (assigned by OCD)
Contact mailing address: 1017 W. Stanolind Road	

Location of Release Source

Latitude 32.720582 Longitude 103.200447
(NAD 83 in decimal degrees to 5 decimal places)

Site Name NHURCF	Site Type OIL AND GAS PRODUCTION FACILITY
Date Release Discovered 07/02/2019	API# (if applicable) N/A

Unit Letter	Section	Township	Range	County
H	25	18-S	37-E	LEA

Surface Owner: State Federal Tribal Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Natural Gas	Volume Released (Mcf) 1311MCF	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

E TRAIN WAS TAKEN DOWN TO REPAIR MOTOR START ISSUES IN THE MCC


Received by OCD: 7/8/2019 2:58:45 PM

Incident ID	pDHR1919036410
District RP	1RP-5611
Facility ID	fAB1909457353
Application ID	nDHR1919037288

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? EXCEEDED 500MCF
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? YES, CHAD DENNIS TO JIM GRISWOLD VIA E-MAIL ON 7/3/2019	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.
If all the actions described above have <u>not</u> been undertaken, explain why: STEPS: 2-4 WAS NOT APPLICABLE.
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.
Printed Name: <u>CHAD DENNIS</u> Title: <u>HES SPECIALIST</u> Signature:  Date: <u>7/2/19</u> email: <u>CHAD_DENNIS@OXY.COM</u> Telephone: <u>432-758-8614</u>
<u>OCD Only</u> Received by: <u>Dylan Rose-Coss</u> Date: <u>07/09/2019</u>

Incident ID	nDHR1919037288
District RP	1RP-5611
Facility ID	fAB1909457353
Application ID	pDHR1919036410


Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: *Each of the following items must be included in the closure report.*

- A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: CHAD DENNIS Title: HES SPECIALIST
 Signature:  Date: 7/2/19
 email: CHAD_DENNIS@OXY.COM Telephone: 432-758-8614

OCD Only

Received by: Dylan Rose-Coss Date: 07/08/2019

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: Dylan Rose-Coss Date: 07/09/2019
 Printed Name: Dylan Rose-Coss Title: NMOCD District 1 Environmental Specialist

OCCIDENTAL PERMIAN LTD.

Event ID: 96099 **Reporting Employee:** CHAD DENNIS
Lease Name: NORTH HOBBS UNIT RCF/WIB **Account Number:** 2415
Equipment: RCF FLARE **NSR Permit Number:** 2656-M5
EPN: RCF - FLR - SSM **Title V Permit Number:**
EPN Name: RCF FLARE SSM EVENTS **Reg Lease Number:**
Flare Point: RCF-FLR-SSM

Explanation of the Cause:

E TRAIN WAS TAKEN DOWN TO REPAIR MOTOR START ISSUES IN THE MCC

Event Type

Malfunction
Malfunction

Corrective Actions Taken to Minimize Emissions:

OPERATIONS CONTACTED ELECTRICIAN TO REPAIR THE ISSUE IN THE MCC BUILDING, BROUGHT E TRAIN BACK ONLINE AND OUT OF THE FLARE

Actions taken to prevent recurrence:

OPERATIONS CONTACTED ELECTRICIAN TO REPAIR THE ISSUE IN THE MCC BUILDING, BROUGHT E TRAIN BACK ONLINE AND OUT OF THE FLARE

Emission Start Date	Emission End Date	Duration
7/2/2019 1:09:00 PM	7/2/2019 3:45:00 PM	2:36 hh:mm

NMED

Pollutant	Duration (hh:mm)	Avging Period	Excess Emission	Number of Exceedances	Permit Limit	Average Emission Rate		Total Pounds	Tons Per Year		
									Total	Next Drop off Date	Date Permit Exceeded
CO	2:36	1	0 LBS	0	152.10	104.07	LBS/HR	270.58	0.135293	7/7/2019	
H2S	2:36	1	0 LBS	0	14.60	5.72	LBS/HR	14.87	0.007439	7/7/2019	
NOX	2:36	1	0 LBS	0	27.10	12.13	LBS/HR	31.55	0.015779	7/7/2019	
SO2	2:36	1	0 LBS	0	1372.10	527.79	LBS/HR	1372.27	0.686139	7/7/2019	
VOC	2:36	1	0 LBS	0	216.70	45.6	LBS/HR	118.58	0.059292	7/7/2019	

Reporting Status: Non-Reportable

NMOCD

Flare Stream Total	Total MCF	EPN	Latitude	Longitude	Reporting Status
1055 MCF	1311 MCF	RCF FLARE SSM EVENTS	32°43'14.96"	103°11'59.65"	Major Release

LEPC

Total MCF	H2S %	Unit Letter	Section	Township	Range
1311	0.786	H	25	18 S	37 E

Emissions Calculations:

NOx = MCF flared x NOx factor from RG-109 x BTU/scf x 1000 scf/MCF x MMBTU/1000000 BTU

CO = MCF flared x CO factor from RG-109 x BTU/scf x 1000 scf/MCF x MMBTU/1000000 BTU

Gas was flared to reduce the hydrocarbon and/or H2S emissions to the atmosphere.

NMNE NG = MCF flared x 50 lb/mole x mole/.379 MCF x mol % NMNE NG x 0.02

NMNE NG % = 100% - Methane % - Ethane % - Carbon Dioxide % - Nitrogen %

H2S = MCF flared x 34 lb/mole x mole/.379 MCF x mol % H2S/100 x 0.02

SO2 = MCF flared x 64 lb/mole x mole/.379 MCF x mol % H2S/100 x 0.98

OCCIDENTAL PERMIAN LTD.

Event ID: 96099	Reporting Employee: CHAD DENNIS
Lease Name: NORTH HOBBS UNIT RCF/WIB	Account Number: 2415
Equipment: RCF FLARE	NSR Permit Number: 2656-M5
EPN: RCF - FLR - SSM	Title V Permit Number:
EPN Name: RCF FLARE SSM EVENTS	Reg Lease Number:
Flare Point: RCF-FLR-SSM	

Explanation of the Cause:

E TRAIN WAS TAKEN DOWN TO REPAIR MOTOR START ISSUES IN THE MCC

Event Type

Malfunction
Malfunction
Malfunction

Corrective Actions Taken to Minimize Emissions:

OPERATIONS CONTACTED ELECTRICIAN TO REPAIR THE ISSUE IN THE MCC BUILDING, BROUGHT E TRAIN BACK ONLINE AND OUT OF THE FLARE

Actions taken to prevent recurrence:

OPERATIONS CONTACTED ELECTRICIAN TO REPAIR THE ISSUE IN THE MCC BUILDING, BROUGHT E TRAIN BACK ONLINE AND OUT OF THE FLARE

Emission Start Date	Emission End Date	Duration
7/2/2019 1:09:00 PM	7/2/2019 3:45:00 PM	2:36 hh:mm

NMED

Pollutant	Duration (hh:mm)	Avging Period	Excess Emission	Number of Exceedances	Permit Limit	Average Emission Rate		Total Pounds	Tons Per Year		
									Total	Next Drop off Date	Date Permit Exceeded
CO	2:36	1	0 LBS	0	152.10	104.07	LBS/HR	270.58	0.135293	7/7/2019	
H2S	2:36	1	0 LBS	0	14.60	5.72	LBS/HR	14.87	0.007439	7/7/2019	
NOX	2:36	1	0 LBS	0	27.10	12.13	LBS/HR	31.55	0.015779	7/7/2019	
SO2	2:36	1	0 LBS	0	1372.10	527.79	LBS/HR	1372.27	0.686139	7/7/2019	
VOC	2:36	1	0 LBS	0	216.70	45.6	LBS/HR	118.58	0.059292	7/7/2019	

Reporting Status: Non-Reportable

NMOCD

Flare Stream Total	Total MCF	EPN	Latitude	Longitude	Reporting Status
1055 MCF	1311 MCF	RCF FLARE SSM EVENTS	32°43'14.96"	103°11'59.65"	Major Release

LEPC

Total MCF	H2S %	Unit Letter	Section	Township	Range
1311	0.786	H	25	18 S	37 E

Emissions Calculations:

NOx = MCF flared x NOx factor from RG-109 x BTU/scf x 1000 scf/MCF x MMBTU/1000000 BTU

CO = MCF flared x CO factor from RG-109 x BTU/scf x 1000 scf/MCF x MMBTU/1000000 BTU

Gas was flared to reduce the hydrocarbon and/or H2S emissions to the atmosphere.

NMNE NG = MCF flared x 50 lb/mole x mole/.379 MCF x mol % NMNE NG x 0.02

NMNE NG % = 100% - Methane % - Ethane % - Carbon Dioxide % - Nitrogen %

H2S = MCF flared x 34 lb/mole x mole/.379 MCF x mol % H2S/100 x 0.02

SO2 = MCF flared x 64 lb/mole x mole/.379 MCF x mol % H2S/100 x 0.98