

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 9/29/2015

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: 10" Water transfer mainline. The spill location is 160 ft. S.W. of the PLU-213 SWD well (2RP-2042)	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No.30-015-33859

LOCATION OF RELEASE

Unit Letter P	Section 18	Township 24S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County: Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	-----------------

Latitude N 32.212260 Longitude W 103.914606

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 12 bbls.	Volume Recovered: 0 bbls.
Source of Release: Flange connection on 10" mainline	Date and Hour of Occurrence: 10/28/13 time unknown	Date and Hour of Discovery: 10/28/13 at 11:47 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A flange on the 10" mainline developed a leak due to loose flange bolts, the bolts were re-torqued and the line was pressure tested.		
Describe Area Affected and Cleanup Action Taken.* Approximately 240 sq.ft. of pasture was affected by the release, all of the fluid soaked into the ground. The area around the leak point was excavated and stockpiled on-site pending removal. The remediation will be in accordance to the NMOCD and BLM guidelines. Basin Environmental conducted a sampling event 1/19/15, the release point and pasture area were tested and found to be below the remediation action level for chlorides. Please find the attached Remediation Summary and Site Closure Request dated September 2015.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist:	
Title: Waste Management and Remediation Specialist	Approval Date: 9/30/2015	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com	Conditions of Approval: FINAL	Attached <input checked="" type="checkbox"/>
Date: 9/29/15	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

2RP-2042