

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Avenue, Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised October 10, 2003

Submit 2 Copies to appropriate
 District Office in accordance
 with Rule 116 on back
 side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Burnett Oil Co., Inc.	Contact	Leslie Garvis
Address	801 Cherry Street - Suite 1500, Ft. Worth, TX 76102	Telephone No.	817-583-8730
Facility Name	Gissler B 3-3 Tank Battery /API# 30-015-41276	Facility Type	Tank Battery
Surface Owner	BLM	Mineral Owner	BLM
		Lease No.	NMNM-2748

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	11	17S	30E	441'	South	467'	West	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE


Type of Release	Fire	Volume of Release	350 bbls	Volume Recovered	None-burned
Source of Release	Heater Treater Fire	Date and Hour of Occurrence	1/19/15	Date and Hour of Discovery	1/19/15 1716 MST
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	BLM- Jim Amos; OCD - H. Patterson (By voicemail and email)		
By Whom?	Leslie Garvis	Date and Hour	1/19/15 approx 1800 MST		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
 The fire is believed to have started in the main production heater treater and spread to the other heaters and separators. No tanks were involved. Flowlines were destroyed. There was a release of approximate 350 bbls of liquid (combination of oil and water) but there is no way for us to determine the amounts of each as the fluid burned during the fire.

Describe Area Affected and Cleanup Action Taken.*
 Soil samples were taken, the area was excavated and the contaminated soil was hauled to an approved disposal. The pad was rebuilt with a 20 mil liner installed. Fresh topsoil and caliche was brought in for backfill once the battery was rebuilt

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Leslie Garvis	Approved by District Supervisor:	Accepted for Record
Title:	Regulatory Coordinator	Approval Date:	10/30/2015
E-mail Address:	lgarvis@burnettoil.com	Expiration Date:	
Date:	5/7/15	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	817-583-8730	remaining clean up deferred until	

* Attach Additional Sheets If Necessary

site abandonment

2RP-2763