

Bratcher, Mike, EMNRD

From: Walker, Clayton D <CDWalker@dcpmidstream.com>
Sent: Monday, November 02, 2015 9:03 AM
To: Pair, Randal; Blair, Yvonne B; Walker, Clayton D
Cc: Dade, Randy, EMNRD; Bratcher, Mike, EMNRD; Case, Nicholas L; Pudim, David A; tgregsto@blm.gov; Valencia, Israel; Michael, Kelley R
Subject: RE: MM line leak C141 with remediation plan
Attachments: LOCO HILLS MM PIPELINE INITIAL.JPG; Wall and Scrape labs.pdf

Attached you will see the where the MM line mentioned below was remediated. These samples were taken on behalf of DCP by Basin Environmental, and were sent to Cardinal labs for analysis. The sample on scrape number 3 came back higher on chlorides than the rest due to what looks like another past leak that entered the area from a well location. DCP would like to ask for permission to back fill this location. Regards, Clay

Clay Walker
SENM Gathering Construction Supervisor
SENM West I&E Supervisor
5301 Sierra Vista Dr
Carlsbad, NM 88220
Office 575-234-6424
Cell 979-540-9238
CDWalker@DCPmidstream.com

From: Pair, Randal [mailto:rpair@blm.gov]
Sent: Friday, October 16, 2015 4:27 PM
To: Blair, Yvonne B
Cc: randy.dade@state.nm.us; mike.bratcher@state.nm.us; Case, Nicholas L; Pudim, David A; tgregsto@blm.gov; Walker, Clayton D; Valencia, Israel; Michael, Kelley R
Subject: Re: MM line leak C141 with remediation plan

Ms Blair,
BLM approves the general tenor of your clean-up proposal.
I checked with our archeologists, and virtually all of the spill path delineated by my coworker Terry Gregston has been previously surveyed for archeology; so you can skip that step.
Please include Chlorides in your sampling parameters for analysis (in addition to TPH and BTEX). Please obtain my approval of final confirmation samples prior to backfilling. You should obtain and retain all load tickets for contaminated materials disposed off-site.
Like approval of your proposed plan by NM-OCD will also be required.

We have reports from third-parties working in the vicinity that the pipe had been leaking for at least a couple of weeks before another BLM employee discovered it. Some 3rd parties reported getting alarms on H2S personal monitors. For these reasons, the BLM-CFO Safety Officer (Terry Gregston) is concerned about the extended duration of the leak, particularly since any gasses would have been concentrated in a narrow downhill flow path. I believe she will approach you - or higher DCP management - to require DCP to address how it will revise its inspection procedures and line markings to prevent future recurrences. Whatever results from that request should be appended to the final report for this leak, in addition to being reported to Ms Gregston separately.

With the addition of these comments, BLM approves this clean-up proposal.

Randal "Randy" Pair
Envir. Protection Specialist - Realty Compliance
office: 575.234.6240
cell: 575.361.0062
email: rpair@blm.gov

On Fri, Oct 16, 2015 at 9:10 AM, Blair, Yvonne B <YBBlair@dcpmidstream.com> wrote:

Mike

After re-evaluating the spill on the MM line in Loco Hills we have discovered it may be at the 5 barrel impact line. Thus we are providing you with the C141 and the remediation plan. We will be working closely with Randy Pair at the BLM on the remediation. Please contact myself or Nick Case 575-802-5225 if you have any questions.

Yvonne Blair

Compliance Coordinator

DCP Midstream

575-361-2406