

## District I

1625 N. French Dr., Hobbs, NM 88240

## District II

1301 W. Grand Ave., Artesia, NM 88210

## District III

1000 Rio Brazos Road, Aztec, NM 87410

## District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural ResourcesOil Conservation District  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141

Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

## OPERATOR

☒ Initial Report ☐ Final Report

Name of Company DCP Midstream, LP		Contact Jon D. Bebbington
Address P.O. Box 5493, Denver, 80217		Telephone No. (432) 620-4207
Facility Name Parkway Booster		Facility Type Compressor Station
Surface Owner <i>BLM</i>	Mineral Owner	Lease No.

## LOCATION OF RELEASE

Unit Letter	Section <i>34</i>	Township <i>18S</i>	Range <i>31E</i>	Feet from the	North/South Line North	Feet from the	East/West Line East	County Eddy
-------------	----------------------	------------------------	---------------------	---------------	---------------------------	---------------	------------------------	----------------

Latitude

Longitude

## NATURE OF RELEASE

Type of Release Soil	Volume of Release 20.00 bbl/event	Volume Recovered 0.00 bbl/event
Source of Release WWEquipment Emergency Vent	Date and Hour of Release 02/15/2012 6:00 AM	Date and Hour of Discovery 02/15/2012 6:00 AM
Was Immediate Notice Given? <input checked="" type="radio"/> Yes <input type="radio"/> No <input type="radio"/> Not Required	If YES, to Whom? <i>Jim Amos</i>	
By Whom?	Date and Hour <i>2-15-12 AM</i>	
Was a Watercourse Reached? <input type="radio"/> Yes <input checked="" type="radio"/> No	If YES, Volume Impacting the Watercourse 0.00 bbl/event	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* On February 15, 2012 approximately 20 bbls of oil was sprayed from the site emergency vent due to pipeshavings clogging the blowcase dump valve. The oil impacted an area down wind of the vent stack. The affected area is a plume shape beginning at the corner of Parkway booster and spreading east for ~600 ft.		
Describe Area Affected and Cleanup Action Taken.* Operations supervisor contacted our remediation crew (Hungry Horse) to immediately start the clean up due to the livestock in the area. Contractor is making an emergency one call and as soon as it is good we will contain the worst part of the spill with fencing to avoid injury to livestock.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Jon D. Bebbington</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jon D. Bebbington	Approved By District Supervisor:	
Title: Sr Env Eng/Spec	Approval Date:	Expiration Date:
E-mail Address: JDBebbington@dcprmidstream.com	Conditions of Approval:	
Date: 02/15/2012 9:33 AM Phone: (432) 620-4207	Attached <input type="checkbox"/>	

\* Attach additional sheets if necessary

*2-16-12 0945*