

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

fAB1521741013

Release Notification and Corrective Action

nAB1521741553

OPERATOR

Initial Report Final Report

Name of Company Enterprise Field Services LLC <i>PO Box 4324, Houston, TX 77210</i>	Contact Alena Miro
Facility Name Pipeline ROW, Eddy County Trunk A <i>Gathering Lateral *2RP-3187*</i>	Facility Type: Gas Gathering Pipeline
Telephone No. 575-706-4926	

Surface Owner Bureau of Land Management	Mineral Owner NA - Pipeline	Lease No. NA
---	---------------------------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	8	23S	31E	47	South	343	West	Eddy

Latitude: N32.315501 Longitude: W-103.803016

NATURE OF RELEASE


Type of Release Natural Gas, Pipeline Liquids	Volume of Release: 441 MCF, 17 BBL Liquids	Volume Recovered: N/A
Source of Release Pipeline Leak.	Date and Hour of Occurrence 07/30/2015 @ 13:00 MDT	Date and Hour of Discovery 07/30/2015 @ 13:00 MDT
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Pipeline leak was discovered by Enterprise operations. Pipeline segment was isolated, blown down and clamped; leaking portion was repaired following standard One-Call.

Describe Area Affected and Cleanup Action Taken.*
Liquid spill occurred within pipeline ROW with liquid overspray outside of ROW. Cleanup activities were carried out in accordance with Enterprise's General Release Notification, Response and Remediation Plan (dated March 9, 2015) and the attached closure plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jon E. Fields	Approved by District Supervisor: MBratcher	
Title: Director, Field Environmental	Approval Date: 9/8/16	Expiration Date: N/A
E-mail Address: jefields@eprod.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 9/7/2016 Phone: 713-381-6684	FINAL	

* Attach Additional Sheets If Necessary

2RP-3187