

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Chevron USA	Contact	Josepha DeLeon
Address	6301 Deauville Blvd, Midland, TX 79706	Telephone No.	575-263-0424
Facility Name	Greenwood PGU #4 Battery	Facility Type	Tank Battery

Surface Owner	BLM	Mineral Owner		API No.	30-015-05616
---------------	-----	---------------	--	---------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	27	18S	31E	600	North	660	West	Eddy

**Latitude** N 32.720010 **Longitude** -W 103.849308

**NATURE OF RELEASE**

Type of Release: Oil	Volume of Release 227.30 bbls	Volume Recovered 165 bbls
Source of Release: Tank Bottom Failed	Date and Hour of Occurrence 09/05/2016 @ unknown	Date and Hour of Discovery 09/05/2016
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jaime Keyes, NMOCD Jim Amos, BLM	
By Whom? Josepha DeLeon	Date and Hour 09/05/2016	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Not Applicable

Describe Cause of Problem and Remedial Action Taken.\*

Leak from oil tank resulted in the release of contents to containment. A vacuum truck was dispatched to collect standing fluid.

Describe Area Affected and Cleanup Action Taken.\*

Affected area included containment area with small adjacent area outside of the berm (~0.87 bbl of oil leaked outside of the berm). A vacuum truck was called to the location and recovered 165 barrels.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b><u>OIL CONSERVATION DIVISION</u></b>	
	Approved by Environmental Specialist:	
Printed Name: Josepha DeLeon	Approval Date:	Expiration Date:
Title: HES Compliance Support - Environmental	Conditions of Approval:	
E-mail Address: jdx@chevron.com	Attached <input type="checkbox"/>	
Date: 09/20/2016	Phone: 575-263-0424	

\* Attach Additional Sheets If Necessary