### Bratcher, Mike, EMNRD

From: Bratcher, Mike, EMNRD

Sent: Wednesday, March 22, 2017 8:07 AM

**To:** 'Blaney, Karolina'; Weaver, Crystal, EMNRD; 'stucker@blm.gov'

**Subject:** RE: WPX RDU 33 - final C-141 report

RE: WPX \* RDU 33 \* 2RP-4108 \* DOR: 1/2/17

Karolina,

OCD requests removal of material in the spill path, through the 6" interval. Once completed, let me know via email and this incident will be approved for closure.

If you have any questions or concerns, please contact me.

Thank you,

Mike Bratcher NMOCD District 2 811 South First Street Artesia NM 88210 575-748-1283 Ext 108 mike.bratcher@state.nm.us

From: Blaney, Karolina [mailto:Karolina.Blaney@wpxenergy.com]

Sent: Monday, March 20, 2017 3:08 PM

To: Weaver, Crystal, EMNRD < Crystal. Weaver@state.nm.us>; 'stucker@blm.gov' < stucker@blm.gov>; Bratcher, Mike,

EMNRD <mike.bratcher@state.nm.us>
Subject: WPX RDU 33 - final C-141 report

Good afternoon,

Attached is the Final C-141 spill closure request. Please let me know if I need to make any revisions. Thank you and have a great afternoon,

#### Karolina Blaneu

Environmental Specialist WPX Energy

Office: (575) 885-7514 Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

From: Weaver, Crystal, EMNRD [mailto:Crystal.Weaver@state.nm.us]

Sent: Tuesday, February 21, 2017 1:33 PM

To: Blaney, Karolina < Karolina.Blaney@wpxenergy.com >; 'stucker@blm.gov' < stucker@blm.gov >; Bratcher, Mike,

EMNRD < mike.bratcher@state.nm.us >

Subject: [EXTERNAL] RE: WPX RDU 33 - initial C-141 report

CAUTION: This email was sent from an EXTERNAL source. Use caution when clicking links or opening attachments.

RE: WPX \* RDU #33 \* 30-015-040623 \* 2RP-4108

Karolina,

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval. The OCD tracking number for this event is 2RP-4108.

Thank you,

## **Crystal Weaver**

Environmental Specialist OCD – Artesia District II 811 S. 1<sup>st</sup> Street Artesia, NM 88210

Office: 575-748-1283 ext. 101

Cell: 575-840-5963 Fax: 575-748-9720

From: Blaney, Karolina [mailto:Karolina.Blaney@wpxenergy.com]

Sent: Thursday, January 26, 2017 3:19 PM

To: 'stucker@blm.gov' <<u>stucker@blm.gov</u>>; Bratcher, Mike, EMNRD <<u>mike.bratcher@state.nm.us</u>>; Weaver, Crystal,

EMNRD < <a href="mailto:crystal.Weaver@state.nm.us">Crystal.Weaver@state.nm.us</a> **Subject:** WPX RDU 33 - initial C-141 report

Good afternoon,

Attached is the initial C-141 for the RDU 33 produced water spill.

Thank you,

# Karolina Blaney

Environmental Specialist

WPX Energy

Office: (575) 885-7514 Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

From: Blaney, Karolina

Sent: Friday, January 13, 2017 11:29 AM

To: 'stucker@blm.gov' <<u>stucker@blm.gov</u>>; 'Bratcher, Mike, EMNRD' <<u>mike.bratcher@state.nm.us</u>>; 'Weaver, Crystal,

EMNRD' < Crystal. Weaver@state.nm.us >

Subject: RE: WPX RDU 12 - initial spill notification

#### Good morning,

WPX had a spill yesterday, 1/12/17, at the RDU 33 tank battery; 30-015-40623 J-22-26S-30E. The spill was caused by human error. A valve on the unloading line was left open which resulted in a 100 bbl spill into lined SPCC containment. Unfortunately, the liner has a hole on the southeast corner and a small volume (less than 1 bbl) leaked out of the containment. I will submit the C-141 report within 15 days of the incident. Thank you and have a great weekend,

## Karolina Blaney

Environmental Specialist WPX Energy

Office: (575) 885-7514 Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

From: Blaney, Karolina

Sent: Thursday, January 12, 2017 8:33 AM

To: 'stucker@blm.gov' <<u>stucker@blm.gov</u>>; 'Bratcher, Mike, EMNRD' <<u>mike.bratcher@state.nm.us</u>>; 'Weaver, Crystal,

EMNRD' < <a href="mailto:Crystal.Weaver@state.nm.us">Crystal.Weaver@state.nm.us</a> <a href="mailto:Subject: WPX RDU 12">Subject: WPX RDU 12</a> - initial spill notification

#### Good morning,

WPX had a spill yesterday, 1/11/17, caused by human error; stuffing box failure. Approximately 12 bbls of oil and water was spilled with 4.5 bbls recovered from the pad. The spill migrated west of the pad, entered a dry drainage and migrated for about 100 yards. Due to access constraints, we were unable to vacuum the free standing oil from the drainage. To prevent from further migration, the oil was absorbed with dirt. The impacted area was GPS-ed and the end of the impacts in the drainage was additionally marked with a flag. We will start the excavation activities once I receive your approval. The line locate call was placed yesterday and we should be ready to go by Monday.

Please let me know if you would like an onsite prior to the excavation activities. We will do our best to minimize the impacts but, unfortunately, I think we will damage some vegetation during this cleanup.

Please let me know if you have any comments and suggestions. Thank you for your help,

## Karolina Blaney

Environmental Specialist WPX Energy

Office: (575) 885-7514 Cell: (970) 589-0743

karolina.blaney@wpxenergy.com