## **Bratcher, Mike, EMNRD**

From: Blaney, Karolina < Karolina.Blaney@wpxenergy.com>

**Sent:** Tuesday, February 21, 2017 6:37 AM

**To:** Tucker, Shelly

Cc: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Raley, Jim Subject: RE: [EXTERNAL] Re: WPX RDX 17-20 spill remediation

Hey Shelly,

We did the initial screening of the impacted area and would like to ask for your permission to remove the top 2' of the impacted soil. Once the soil is removed, we will continue our delineation.

Please let me know if you're OK with that.

Thank you,

## Karolina Blaney

Environmental Specialist

WPX Energy

Office: (575) 885-7514 Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

From: Blaney, Karolina

**Sent:** Thursday, February 16, 2017 11:42 AM **To:** 'Tucker, Shelly' <stucker@blm.gov>

Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>;

Raley, Jim <jim.raley@wpxenergy.com>

Subject: RE: [EXTERNAL] Re: WPX RDX 17-20 spill notification

#### Good morning Shelly,

We were going to do an initial delineation for salts and hydrocarbons of the impacted area that's off the location. Are we OK to scrape off the top 1 or 2 feet for now and do a more thorough cleanup after we get some sampling and screening completed? I checked our GIS data and there are no significant/sensitive areas directly north of the RDX 17-20 pad. Thank you,

## Karolina Blaney

**Environmental Specialist** 

WPX Energy

Office: (575) 885-7514 Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

From: Tucker, Shelly [mailto:stucker@blm.gov]
Sent: Thursday, February 16, 2017 10:55 AM

To: Blaney, Karolina < Karolina.Blaney@wpxenergy.com>

Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>

Subject: [EXTERNAL] Re: WPX RDX 17-20 spill notification

CAUTION: This email was sent from an EXTERNAL source. Use caution when clicking links or opening attachments.

## Thank you for the notification.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly G Tucker

Environmental Protection Specialist O&G Spill/Release Coordinator

Bureau of Land Management 620 E. Greene St Carlsbad. NM 88220

575.234.5905 - Direct 575.361.0084 - Cellular

575.234.6235 - Emergency Spill Number

stucker@blm.gov

The <u>BLM acceptance/approval does not</u> relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

<u>Confidentiality Warning:</u> This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Fri, Feb 10, 2017 at 2:21 PM, Blaney, Karolina < Karolina. Blaney@wpxenergy.com > wrote:

Good afternoon,

This morning, WPX had a spill at the RDX 17-20 well pad; API #3001541381, qtr/qtr A, Sec. 17 T26S R30E. The cause of the spill is mechanical failure; a hose on a charge pump was exposed to constant vibration and developed a hole. Approximately 400 bbls of produced water got spilled with 100 bbls recovered with a vacuum truck. Some of the spilled fluids migrated to the north of the well pad and impacted an area of  $^{\sim}100'x100'$ .

The C-141 report will be submitted within the next 15 days however, please feel free to contact me with any questions or concerns.

Thank you and have a great weekend,

# Karolina Blaney

**Environmental Specialist** 

WPX Energy

Office: (575) 885-7514

Cell: (970) 589-0743

karolina.blaney@wpxenergy.com