

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

(*revision*)
☒ Initial Report

☐ Final Report

Name of Company	J. Cleo Thompson	Contact	Amador Pando, Production Foreman
Address	117 West Yukon, Odessa, TX 79764	Telephone No.	(432) 664-2578
Facility Name	West Square Lake Unit (WSLU) Tract 003 Well #9	Facility Type	Production
Surface Owner	Federal	Mineral Owner	
		API No.	3001503967

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	33	16S	30E	1980	FSL	660	FEL	Eddy

Latitude 32.87723° N Longitude -103.97278° W

NATURE OF RELEASE


Type of Release	Well Fluids (from three wells going to satellite battery)	Volume of Release	Est. 5-10 bbl	Volume Recovered	0 bbl
Source of Release	Hole in flowline	Date and Hour of Occurrence	Just prior to discovery	Date and Hour of Discovery	May 26, 2016 (hour unknown)
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Unknown. BLM Natural Resource Specialist made initial release notification. The Specialist also notified Amador Pando, Production Foreman with J. Cleo Thompson.		
By Whom?	BLM Natural Resource Specialist made initial release notification.	Date and Hour	May 26, 2016 (hour unknown)		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	n/a		

If a Watercourse was Impacted, Describe Fully.*
The release did not impact a watercourse.

Describe Cause of Problem and Remedial Action Taken.* The release was caused by a hole in a flowline that was discovered by the BLM's Natural Resource Specialist ("Specialist") on Thursday, May 26, 2016. The Specialist notified J. Cleo Thompson ("J. Cleo") of the release. The release source was remedied resulting in a minimal impact footprint due to low release volumes. On May 27, 2016, the BLM and J. Cleo performed a joint release evaluation at the site. Sport Environmental Services, LLC (environmental consultant) performed initial remedial efforts at the release site on Monday, May 30, 2016. Based upon visual assessment, *Micro-Blaze* was applied to the hydrocarbon impacted-areas at the site where residual impact was present (no free liquids). Attached please find a site plan denoting area impacted and *Micro-Blaze* application quantities. The BLM would like to perform an archeology study in the immediate release area prior to any further remedial efforts and potential soils disturbance by J. Cleo Thompson.

Describe Area Affected and Cleanup Action Taken.* The affected area is remote in location. The flowline was moving well fluids from three wells to a satellite battery to be ultimately transferred to the consolidated battery location. A hole in flowline resulting in an estimated well fluids loss of 5-10 bbl. Product was adsorbed into surficial soils resulting in non-recovery of released fluids. Impacted area is roughly 1,704 square feet. *Micro-Blaze* treatment was applied on 575 square feet (34%) of the affected area. See the section above for a complete description of remedial and cleanup actions taken to date. See attached site plan (demarcated aerial imagery) for release specifics.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Deborah S. Moore, Agent for J. Cleo Thompson		Approved by Environmental Specialist:	
Title: President of Sport Environmental Services, LLC		Approval Date:	Expiration Date:
E-mail Address: debi@sportenv.com		Conditions of Approval:	
Date: July 7, 2016 Phone: (432) 683-1100/(432) 553-8555 cell		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary