

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 4/13/2018  
NMOCD Dist 2

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

fAB1736133556

## Release Notification and Corrective Action

nAB1803253706

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: <b>COG Operating, LLC</b> (OGRID# 229137)	Contact: <b>Robert McNeill</b>
Address: <b>600 West Illinois Avenue, Midland TX 79701</b>	Telephone No.: <b>432-683-7443</b>
Facility Name: <b>Marsh Owl CTB</b>	Facility Type: <b>Central Tank Battery</b>

Surface Owner: BLM	Mineral Owner: BLM	API No.:
--------------------	--------------------	----------

### LOCATION OF RELEASE

Unit Letter G	Section 13	Township 26S	Range 26E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude: 32.045226 Longitude: -104.245834 NAD83

### NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 29 bbls	Volume Recovered: 27 bbls
Source of Release: Valve	Date and Hour of Occurrence: 1/28/2018	Date and Hour of Discovery: 1/28/2018 11:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Crystal Weaver NMOCD & Shelly Tucker BLM	
By Whom? Becky Haskell	Date and Hour: 1/28/2018 12:05 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The release was caused by an equalizer line being left in the closed position.

Describe Area Affected and Cleanup Action Taken.\*

All of the fluid remained inside of the lined containment. A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

 Signature:		<b><u>OIL CONSERVATION DIVISION</u></b>	
		Approved by Environmental Specialist: 	
Printed Name: Dakota Neel			
Title: HSE Coordinator		Approval Date: 4/13/2018	Expiration Date: N/A
E-mail Address: dneel2@concho.com		Conditions of Approval: Like approval BLM	Attached <input type="checkbox"/>
Date: 4-13-2018 Phone: 575-746-2010			

\* Attach Additional Sheets If Necessary

2RP-4596