

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1809434279

OPERATOR
 Initial Report Final Report

Name of Company Marathon Oil Permian LLC	Contact Callie Karrigan
Address 5555 San Felipe Street, Houston, Texas 77056	Telephone No. 405-202-1028 (cell) 575-297-0956 (office)
Facility Name: Southern Comfort 25 36 State X No. 001H	Facility Type Oil and gas production facilities

Surface: Owner: state	Mineral: Owner: state	API No. : 30-015-44332
-----------------------	-----------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	25	24S	28E	2490	South	2310	East	Eddy

Latitude 321882. Longitude -104.0400

NATURE OF RELEASE

Type of Release: Fire	Volume of Release: 5 gallons	Volume Recovered: 2.5 gallons
Source of Release: flare	Date and Hour of Occurrence 01/25/2018 04:00 am	Date and Hour of Discovery 01/25/2018 04:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Crystal Weaver – Eddy County	
By Whom? Callie Karrigan	Date and Hour 01/25/2018 09:40 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
Not applicable.

Describe Cause of Problem and Remedial Action Taken.*

Flowback Operators were onsite working on well when they observed a small fire by beside the completions flare. The fire was immediately extinguished by the Flowback Operators. Upon further investigation, it was discovered that the line had frozen due to cold temperatures and a small amount of condensate and methanol in the line exited the flare. Flowback Operators are now monitoring condensate levels in the knockouts. Trap drains and additional piping were installed on all temporary flares.

Describe Area Affected and Cleanup Action Taken.*

The affected area was around the base of the flare in a 5'x10' area. The affected area will be scraped and a confirmation sample will be taken and analyzed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Callie Karrigan Signature:	<u>OIL CONSERVATION DIVISION</u>	
	Approved by Environmental Specialist: 	
Printed Name: Callie Karrigan	Approval Date: 4/25/18	Expiration Date: N/A
Title: HES Environmental Professional	Conditions of Approval: N/A	
E-mail Address: cnkarrigan@marathonoil.com	FINAL	Attached <input type="checkbox"/>
Date: 4/13/2018 Phone: 405-202-1028(cell) 575-297-0956 (office)		

* Attach Additional Sheets If Necessary

2RP-4689

Post Incident



Post Clean-up

