

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised April 3, 2017

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: XTO Energy BOPCO OGRID: 260737	Contact: Kyle Littrell
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No: 432-221-7331
Facility Name: North Indian Flats 26 Federal #1	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No: 30-015-27556	

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	26	21S	28E	2150	North	1980	East	Eddy

Latitude 32.452295 Longitude -103.054719 NAD83

### NATURE OF RELEASE

Type of Release Oil	Volume of Release 7bbl oil	Volume Recovered 4bbl oil
Source of Release Oil tank	Date and Hour of Occurrence 7/26/2018, 10:00 AM	Date and Hour of Discovery 7/26/2018, 10:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour: N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A


Describe Cause of Problem and Remedial Action Taken.\*

Crew was attempting to remove flowline from oil tank on location. Upon striking hammer union, threads connecting valve and swedge cracked, causing a release of oil into earthen containment. Vacuum truck was dispatched and recovered all standing fluid. Damaged connection was repaired and all recovered oil was returned to oil tank.

Describe Area Affected and Cleanup Action Taken.\*

All fluid was contained to earthen berm. Vacuum truck was dispatched and recovered 4bbl standing fluid from berm. An environmental contractor has been retained to assist with remediation efforts.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Amy C. Ruth	Approved by Environmental Specialist: Maria Pruett	
Title: Environmental Coordinator	Approval Date: 08/10/18	Expiration Date: N/A
E-mail Address: Amy_Ruth@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/9/2018 Phone: 575-689-3380		2RP-4912

\* Attach Additional Sheets If Necessary

I#:nMAP1822267131

A#:pMAP1822266963