

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCD Rec'd:08/22/18

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Holly Energy Partners OGRID 282505	Contact	Melanie Nolan
Address	1602 W Main	Telephone No.	214-605-8303
Facility Name	Pump Colgate Osage Lease	Facility Type	pump
Surface Owner	BLM	Mineral Owner	BLM
		API No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	34	19S	29E					Eddy

Latitude 32.618708 Longitude -104.061213 NAD83

NATURE OF RELEASE

Type of Release	Crude	Volume of Release	15 barrels	Volume Recovered	0
Source of Release	Pump	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	8/21/18 1202 MST
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	BLM was notified. Both verbal and email notifications were made.		
By Whom?	Melanie Nolan	Date and Hour:	08/21/18 at 3.00 pm MST		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

HEP technicians discovered that an HEP pump was leaking in the vicinity of the Colgate Osage Lease. The leak was due to the packing going bad in the pump. Approximately 15 barrels were released.

Describe Area Affected and Cleanup Action Taken.*

The area affected runs from the pump out in a circular pattern that narrows as it proceeds further out approximately 150ft with soil penetration ranging from 4" to 2' where oil pooled. Crews have started excavating contaminated soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Vikrant Chavan	Approved by Environmental Specialist: 		
Title: Environmental Specialist III	Approval Date: 08/22/18	Expiration Date: N/A	
E-mail Address: Vikrant.Chavan@hollyenergy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 8/22/18 Phone: 214-954-6682	N/A		2RP-4947

* Attach Additional Sheets If Necessary

FID: fMAP1823450708 I#: nMAP1823450982 A#: pMAP1823451961