

Bratcher, Mike, EMNRD

From: Mann, Ryan <rmann@slo.state.nm.us>
Sent: Wednesday, August 8, 2018 10:24 AM
To: 'Adrian Baker'; Bratcher, Mike, EMNRD; Pruett, Maria, EMNRD
Cc: Littrell, Kyle; Ashley Ager
Subject: RE: Backfill/Closure request JRU 76/2RP-4715

NMSLO approves backfill. I cannot tell from the map due to some many points being in the same area...the area around FS12 is excavated to 6'? Can you confirm? Also [SW12@2.5'](#) is high for chlorides; SW14A@2' is not. Is SW14A 2 feet below SW14? Can you clarify?

Ryan Mann
Remediation Specialist
Field Operation Division
(575) 392-3697
(505) 699-1989
New Mexico State Land Office
2827 N. Dal Paso Suite 117
Hobbs, NM 88240

From: Adrian Baker [mailto:abaker@ltenv.com]
Sent: Monday, August 6, 2018 3:44 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Pruett, Maria, EMNRD <Maria.Pruett@state.nm.us>; Mann, Ryan <rmann@slo.state.nm.us>; Naranjo, Mark <MNaranjo@slo.state.nm.us>
Cc: Littrell, Kyle <Kyle_Littrell@xtoenergy.com>; Ashley Ager <aager@ltenv.com>
Subject: Backfill/Closure request JRU 76/2RP-4715

All,

Please find the attached report and closure request documenting remediation conducted at the JRU 76. The work was conducted to address the recent spill with the RP number of 2RP-4715. XTO is requesting backfill/closure approval from the NMOCD and SLO.

Please let us know if you have any questions, you can contact myself or Kyle Littrell at XTO.

Thank you
Adrian Baker
Project Geologist



LT Environmental, Inc.
3300 North A Street, Building 1, #103
Midland , Texas 79705
(432) 704-5178 office
(432) 894-5641 cell

(432) 704-5179 fax

www.ltenv.com

Connect with us:



This message and any attached files are privileged, confidential, and intended solely for the use of the addressee. If you have received this by mistake, please let us know by reply e-mail and delete it from your system; you may not copy, disclose, disseminate, use or rely upon its content for any use. E-mail transmissions cannot be guaranteed to be secure, error-free, or free of viruses. The sender and LTE therefore do not accept liability for any of these described issues. The comments and opinions expressed herein are those of the author and not necessarily of LTE. Thank you.



Please consider the environment before printing this e-mail.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>
