

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

Initial Report    ☒ Final Report

Name of Company: Burnett Oil Co., Inc.	Contact: Johnny Titsworth
Address: Burnett Plaza-Ste 1500, 801 Cherry St-Unit 9, Fort Worth, TX 76102	Telephone No. (432) 425-2891
Facility Name: Nosler 12 Fed Tank Battery	Facility Type: Tank Battery
Surface Owner: BLM	Mineral Owner: BLM
API No. 30-015-43421	

### LOCATION OF RELEASE

Unit Letter G	Section 11	Township 17S	Range 31E	Feet from the 1800	North/South Line FNL	Feet from the 300	East/West Line FEL	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude: 32.82728 Longitude: -103.86566

### NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 40 Oil	Volume Recovered: 33 Oil
Source of Release FWKO & Flare Stack	Date and Hour of Occurrence: 1/19/17 2:00 pm	Date and Hour of Discovery 1/19/17 2:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD – M. Bratcher   BLM – S. Tucker	
By Whom? Johnny Titsworth	Date and Hour: 1/19/17 3:00pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully. *		
N/A		



#### Describe Cause of Problem and Remedial Action Taken. \*

High pressure at free water knockout caused pressure relief valve to release oil. All standing fluid was picked up, and equipment was cleaned off. Area will be remediated to regulatory standards.

#### Describe Area Affected and Cleanup Action Taken. \*

there was a 75'x100' overspray area on the Nosler 12 Fed TB location, and a 100'x75' area on the Puckett North 13 lease for Hudson, as well a 50'x1' and a 100'x1'5' fingers with pooling areas. There was also a 400'x200' overspray area. The area on the pad will be scrapped and then the area will be sampled and remediated to regulatory standards.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Johnny Titsworth	Approved by Environmental Specialist: 	
Title: HSE Coordinator	Approval Date: 08/24/18	Expiration Date: N/A
E-mail Address: jtitsworth@burnettoil.com	Conditions of Approval:	
Date: 8/7/18      Phone: (432) 425-2891	Like Approval BLM      Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

**FINAL 2RP-4107**