

## Bratcher, Mike, EMNRD

---

**From:** Raley, Jim <James.Raley@wpxenergy.com>  
**Sent:** Tuesday, July 17, 2018 12:30 PM  
**To:** Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD  
**Cc:** stucker@blm.gov; Blaney, Karolina  
**Subject:** RE: East Pecos 22-5H

RE: RKI/WPX \* East Pecos Fed 22 5H \* **2RP-4673** \* DOR: 3/3/18


Shelly,

We would like to begin remediation on this incident based on the OCD approved workplan. Does the BLM have any additional concerns with the referenced remediation plan?  
Please let me know if you need any additional information.

Jim Raley | Environmental Specialist - Permian Basin

5315 Buena Vista Dr., Carlsbad, NM 88220

C: (575)689-7597 | james.rale@wpxenergy.com



---

**From:** Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]  
**Sent:** Thursday, June 14, 2018 2:03 PM  
**To:** Raley, Jim <James.Raley@wpxenergy.com>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>  
**Cc:** stucker@blm.gov; Blaney, Karolina <Karolina.Blaney@wpxenergy.com>  
**Subject:** [EXTERNAL] RE: East Pecos 22-5H

---

CAUTION: This email was sent from an EXTERNAL source. Use caution when clicking links or opening attachments.

---

RE: RKI/WPX \* East Pecos Fed 22 5H \* **2RP-4673** \* DOR: 3/3/18

Jim,

This proposal for remediation of the above referenced release is approved with the following:

- Any liner placement must be a minimum of 4' bgs.
- Notify the OCD District 2 office once remedial activities have been scheduled.
- Federal sites will require like approval from BLM.

Thank you,

Mike Bratcher  
NMOCD District 2  
811 South First Street  
Artesia, NM 88210  
575-748-1283 Ext 108

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

---

**From:** Raley, Jim <[James.Raley@wpxenergy.com](mailto:James.Raley@wpxenergy.com)>

**Sent:** Wednesday, June 6, 2018 3:33 PM

**To:** Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; Weaver, Crystal, EMNRD <[Crystal.Weaver@state.nm.us](mailto:Crystal.Weaver@state.nm.us)>

**Cc:** [stucker@blm.gov](mailto:stucker@blm.gov); Blaney, Karolina <[Karolina.Blaney@wpxenergy.com](mailto:Karolina.Blaney@wpxenergy.com)>

**Subject:** Re: East Pecos 22-5H

RE: WPX/RKI \* East Pecos Federal 22-5H \* 30-015-42270 \* 2RP-4673

Mr. Bratcher,

Please find attached update and proposed work plan for incident 2RP-4673.

Jim Raley | Environmental Specialist - Permian Basin

5315 Buena Vista Dr., Carlsbad, NM 88220

C: (575)689-7597 | [james.ralej@wpxenergy.com](mailto:james.ralej@wpxenergy.com)

