District [1 1625 N. French Dr., Hobbs, NM 88240 District [] 811 S. First St., Artesia, NM 88210 District III 1000 Rto Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NMAP1828226742
District RP	2RP-4995
Facility ID	fMAP1828226389
Application ID	pMAP1828226893

Release Notification

		Res	ponsi	ble Part	ty
Responsible Party Mai	ador Resources Co	mpany		OGRID 2	228937
Contact Name John Hurt				Contact 1	Celephone 972-371-5200
Contact email 1Hurt@matadorresources.com				Incident A	† (1000gund 100 OCO NMAP1828226742
Contact mailing address5400 LBJ Freeway, Suite 1500 Dallas,TX 75240			J	NWW TOZOZZOTAZ	
73240					
		Location	n of R	elease S	ource
Latitude 32.229609°		3000000		Longitude	-104.083454°
		(NADIO)	en annea den	reste Dans	or requestion of
Site Name TOM MATT				Site Type	Tank Battery
Date Release Discovere	3/19/19/18 00			1MAP1828226389	
Unit Letter Section	Township	Range		Сош	nty
L 10	248	28E	Eddy	Eddy	
Surface Owner: State	- D Federal D T	ribal 🖾 Brivata /	10/	VA DOUIDZ	NOVE NO.
Juriace Owner. [State	C [] redetal [] t				,,
		Nature an	a Vai	umeof	Release
Mater	inf(s) Released (Select a	II that apply and attach	h calculati	ons or specific	justification for the volumes provided below)
Crude Oil	Volume Release	ed (bbls)			Volume Recovered (bbls)
				Volume Recovered (bbis) 280	
Is the concentration of dissolved chloride produced water >10.000 mg/l?		chloride	in the	⊠ Yes □ No	
Condensate Volume Released (bbls)					Volume Recovered (bbis)
Natural Gas Volume Released (Mcf)				Volume Recovered (Mcf)	
Other (describe) Volume/Weight Released (provide units)		e units)		Volume/Weight Recovered (provide units)	
Cause of Release Equipment Failure- Trans	nsfer Pump failed. I	Releasing fluids or	n locatio	n north ea	st and south of tank battery. No fluids left the location
	·			The state of the s	of and south of tank battery. No fluids left the location

State of New Mexico Oil Conservation Division

0.97		
Incident ID	NMAP1828226742	
District RP	2RP-4995	
Facility ID	fMAP1828226389	
Application ID	pMAP1828226893	

Was this a major	If YES, for what reason(s) does the responsible party consider this a major release?				
release as defined by 19.15.29.7(A) NMAC?	The vacuum truck recovered 280 bbls on 9/19/18				
Yes No					
If YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?				
OCD, Jim Griswold, Miki	e Bratcher and Maria Pruett, from SMA -Lucas Middleton by email @2;48 pm on 9/19/18				
	Initial Response				
The responsible p	racty must undertake the following ections immediately unless they could create a safety hazard that would result in injury				
The source of the rele	ase has been stopped.				
The impacted area has	been secured to protect human health and the environment.				
Released materials ha	ve been contained via the use of berms or dikes, absorbent pads, or other containment devices.				
All free liquids and re	coverable materials have been removed and managed appropriately.				
If all the actions described	above have not been undertaken, explain why:				
Per 19.15.29.8 B. (4) NM/	AC the responsible party may commence remediation immediately after discovery of a release. If remediation				
nas begun, please attach a	narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred				
within a lined containment	area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.				
I hereby certify that the inform	mation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and				
regulations all operators are n	equired to report and/or file certain release notifications and perform corrective actions for releases which may endanger ent. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have				
Tailed to adequately investigate and remediate contamination that pose a threat to groundwater surface water, human health or the environment, le					
addition, OCD acceptance of and/or regulations.	a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws				
Printed Name: Signature:	ohn Hunt Title: RES Specialist Date: 10/2/18				
1	Date. 10/2/10				
email:	atadorresources.com Telephone: 972-371-5200				
OCD Only					
	11111				
Received by:	Date: 10/09/2018				