District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAB1901036530
District RP	2RP-5168
Facility ID	fAB1901036001
Application ID	pAB1901036172

## **Release Notification**

Responsible Party							
Responsible Party El Paso Natural Gas Company, L.L.C.					OGRID 7057		
Contact Name Cesar G. Ochoa					Contact Te	Telephone 915-587-3694	
Contact email cesar_ochoa@kindermorgan.com				Incident #	# (assigned by OCD) NAB1901036530		
Contact mailing address 8645 Railroad Dr., El Paso, TX 79904							
Location of Release Source							
Latitude 32.21814				Longitude	le 107.42181ecimal places)		
Site Name	Florida Co	ompressor Station			Site Type Natural Gas Compressor Station		
Date Release Discovered November 5, 2018 @ 8:30 am				API# (if applicable)			
Unit Letter	Section	Township	Range		Coun	inty	
I	14	24S	6W	Luna	County Luna County		
Surface Owner: State Federal Tribal Private (Name: El Paso Natural Gas Company, L.L.C)  Nature and Volume of Release  Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)							
Crude Oil		Volume Release		cii cuicuiu	Volume Recovered (bbls)		
Produced	Water	Volume Release	d (bbls)			Volume Recovered (bbls)	
Is the concentration of dissolved chlorid produced water >10,000 mg/l?		chloride	ride in the Yes No				
Condensate Volume Released (bbls)			Volume Recovered (bbls)				
☐ Natural Gas Volume Released (Mcf)				Volume Recovered (Mcf)			
☑ Other (describe)       Volume/Weight Released (provide units Approximately 300 gallons		e units)	S) Volume/Weight Recovered (provide units)				
Cause of Release Mechanical hydraulic oil pump seal failed on Florida A-01 unit releasing approximately 1500 gallons. 1200 gallons were contained on the building basement and approximately 300 gallons of lube oil were released out of the building into the environment.  Corrective Actions: Contractors were mobilized on November 6, 2018 to begin corrective activities. Impacted soil will be excavated and collected for disposal. In Addition, samples will be collected to determine affected area and confirm cleanup levels.							

## State of New Mexico Oil Conservation Division

Incident ID	NAB1901036530
District RP	2RP-5168
Facility ID	fAB1901036001
Application ID	pAB1901036172

Was this a major release as defined by 19.15.29.7(A) NMAC?  ☐ Yes ☒ No	sible party consider this a major release?					
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?						
Initial Response						
The responsible party must undertake the following actions immediat	ely unless they could create a safety hazard that would result in injury					
☐ The source of the release has been stopped.						
$\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ $	the environment.					
Released materials have been contained via the use of berms or d	ikes, absorbent pads, or other containment devices.					
$\  \  \  \  \  \  \  \  \  \  \  \  \  $	l managed appropriately.					
If all the actions described above have <u>not</u> been undertaken, explain	vhy:					
Per 19.15.29.8 B. (4) NMAC the responsible party may commence rehas begun, please attach a narrative of actions to date. If remedial						
within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), p	• •					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.						
Printed Name:Cesar/G. Ochoa	Title:EHS Engineer II					
Printed Name:Cesar/G. Ochoa Signature:	Date:November 8, 2018					
email: Cesar ochoa@kindermorgan.com	Telephone:915-587-3694					
OCD Only  Received by:	Date: 01/10/2019					