District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAB1902442612
District RP	2RP-5198
Facility ID	fAB1902440237
Application ID	pAB1902440356

Release Notification

Responsible Party

Responsible Party: HollyFrontier Companies LLC**					OGRID# 229137 **#278421		
Contact Name: Katharine E. Boyer					Contact Telephone: 214-954-6515		
Contact emai	il: Katharine	e.Boyer@HollyFro	ontier.com		Incident #	(assigned by OCD)	NAB1902442612
Contact mailing address: 2828 North Hardwood Street, Suite 1300, Dallas, Texas 75201							
			Location	of R	telease S	Source	
Latitude	32.8	6436			Longitude	- 103.96689	
			(NAD 83 in d	ecimal de	egrees to 5 dec	rimal places)	
Site Name: Carmen 3 Federal Com #1H					Site Type: Production Lease Operated by COG		
Date Release Discovered: 1/7/2018 ** **1/07/2019 According to letter				etter	API# (if applicable) 30-015-39286		
				XY D			
Unit Letter	Section	Township	Range	County			
Е	3	17S	30E	Eddy Cou		ounty	
Surface Owner: State Federal Tribal Private (Name: Operator)							
Nature and Volume of Release							
	Materi	al(s) Released (Select	all that apply and attach	n calculat	ions or specifi	ic justification for the	volumes provided below)
Crude Oil	Crude Oil Volume Released (bbls) 275 BBLS					Volume Recovered (bbls) Unknown	
Produced	Water	Volume Released (bbls)				Volume Recove	ered (bbls)
Is the concentration of dissolved chloride			loride	in the	Yes No		
produced water >10,000 mg/l? Condensate Volume Released (bbls)					Volume Recove	ered (hbls)	
					Volume Recove	` _ ´	
Natural Gas Volume Released (Mcf)				Volume/Weight Recovered (provide units)			
Other (describe) Volume/Weight Released (provide units)		units)		Volume/Weigh	t Recovered (provide units)		
Cause of Release: HollyFrontier Companies LLC is submitting this form C-141 on behalf of Transwood Logistics Inc. A Transwood truck driver was loading crude onto his truck at the Concho (COG) production lease, Carmen 3 Federal Com #1H Well, Loco Hills, Eddy County, NM,							
and spilled approximately 275 barrels of crude onto the ground at the lease and across approximately six miles on Highway 82 and County Road 126. The estimate of 275 barrels includes an unknown volume of crude spilled onto HWY 82 and County Road 126. At							
this time, the root cause of the spill is unclear since the Transwood truck driver drove his truck to Transwood's truck yard after the spill							

occurred, parked it in the middle of the night and has disappeared. Transwood is taking the lead on the site characterization and cleanup.

State of New Mexico Oil Conservation Division

Incident ID	NAB1902442612
District RP	2RP-5198
Facility ID	fAB1902440237
Application ID	pAB1902440356

Was this a major release as defined by	If YES, for what reason(s) does the respon	nsible party consider this a major release?				
19.15.29.7(A) NMAC?	Yes, it is considered a major spill based o	n the amount of 275 barrels of crude that was spilled to the ground.				
⊠ Yes □ No						
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc.)?						
It is unclear the details of the call into OCD, since a representative from Concho Resources, INC called in the spill to OCD.						
	Initial F	Response				
The responsible	e party must undertake the following actions immedial	tely unless they could create a safety hazard that would result in injury				
∑ The source of the rele	ease has been stopped.					
☐ The impacted area has been secured to protect human health and the environment.						
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.						
All free liquids and re	ecoverable materials have been removed an	d managed appropriately.				
If all the actions described above have <u>not</u> been undertaken, explain why:						
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.						
regulations all operators are public health or the environmental failed to adequately investigation.	required to report and/or file certain release noti ment. The acceptance of a C-141 report by the Cate and remediate contamination that pose a thre	best of my knowledge and understand that pursuant to OCD rules and fications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have at to groundwater, surface water, human health or the environment. In responsibility for compliance with any other federal, state, or local laws				
and/or regulations.	1					
Printed Name: Katharine	E. Boyer	Title: EHS Manager				
Signance Anthana	ne E Doyor	Date: January 22, 2019				
email: Katharine.Bover@	<u>HollyFrontier.com</u>	Telephone: 214-954-6515				
OCD Owler						
OCD Only						
Received by:	no sotamente	Date:				