

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: XTO Energy OGRID: 5380	Contact: Kyle Littrell
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No: 432-221-7331
Facility Name: Thriller BWL Federal 001H	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No: 30-015-43909	

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	30	25S	29E	354	South	660	East	Eddy

Latitude 32.093055 Longitude -103.998609 NAD83

### NATURE OF RELEASE

Type of Release Oil and produced water	Volume of Release 51bbl produced water, 3bbl oil	Volume Recovered 47bbl produced water, 3bbl oil
Source of Release Flow line	Date and Hour of Occurrence 7/25/2018, AM	Date and Hour of Discovery 7/25/2018, 8:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Maria Pruett (NMOCD), Jim Amos and Shelly Tucker (BLM), Ryan Mann (SLO)	
By Whom? Jake Foust	Date and Hour: 7/26/2018, 1:24 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A


Describe Cause of Problem and Remedial Action Taken.\*

Release was from a flex pipe flowline rubbing and flexing against a rock. The flowline was repaired and is scheduled to be buried to prevent further damage.

Describe Area Affected and Cleanup Action Taken.\*

Fluid impacted pad surface, flowing south toward the center of the location. All fluid stayed on pad and there was no impact to the pasture. Vacuum trucks were dispatched and recovered 50bbl of standing fluid. An environmental contractor has been retained to assist with remediation efforts.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Kyle Littrell		Approved by Environmental Specialist: Maria Pruett	
Title: Environmental Coordinator	Approval Date: 08/11/18	Expiration Date: N/A	
E-mail Address: Kyle.Littrell@xtoenergy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 08-03-18 Phone: 432-221-7331	Confirm location		2RP-4915

\* Attach Additional Sheets If Necessary

A#: pMAP1822341664  
I#: nMAP1822341832