

Bratcher, Mike, EMNRD

From: Baker, Larry <Larry.Baker@apachecorp.com>
Sent: Thursday, December 20, 2018 11:13 AM
To: Mann, Ryan
Cc: Bratcher, Mike, EMNRD; Feather, David
Subject: [EXT] Re: [EXTERNAL] RE: 2 RP-4977 remediation plan

Mr. Mann,

There has been no soil remediation conducted due to the 5 surface samples collected and submitted to the laboratory were under table one standards and therefore do not require delineation. The plan is written so that final samples can be collect and if any are above table one standards those areas will be address in accordance with the remediation plan. If the final samples are below no soil remediation will be conducted and a closure report will be submitted. Please let me know if you have any further questions or wish to discuss. I am currently out of the office and will return on 12/27/18. Thanks and have a good day

Bruce Baker
Apache Corporation

Sent from my iPhone

On Dec 20, 2018, at 11:51 AM, Mann, Ryan <rmann@slo.state.nm.us> wrote:

Mr. Baker,

The way this report is written is confusing to me as written. Please provide some clarification. Was there any initial action taken to remove chloride impacted material? If so, how much was removed. All of the samples came back below the remedial action level. This seems unlikely since there samples were taken to delineate the extent of the spill and their locations within the spill area.

From: Baker, Larry [<mailto:Larry.Baker@apachecorp.com>]
Sent: Thursday, December 6, 2018 1:49 PM
To: Bratcher, Mike, EMNRD (mike.bratcher@state.nm.us) <mike.bratcher@state.nm.us>; Mann, Ryan <rmann@slo.state.nm.us>
Cc: Feather, David <David.Feather@apachecorp.com>
Subject: FW: 2 RP-4977 remediation plan

All,

Attached is the remediation plan with a remediation time line. Please disregard the other plan. Thanks and have a good day.

BRUCE BAKER

ENVIRONMENTAL TECHNICIAN SR
direct 575-393-7106 ext 1523 | Cell 432-631-6982

APACHE CORPORATION
2350 W. MARLAND BLVD
HOBBS, NM 88240

ApacheCorp.com | [LinkedIn](#) | [Facebook](#) | [Twitter](#) | [StockTwits](#) | [YouTube](#)

From: Baker, Larry
Sent: Thursday, December 06, 2018 2:38 PM
To: Bratcher, Mike, EMNRD (mike.bratcher@state.nm.us) ; Mann, Ryan
Cc: Feather, David
Subject: 2 RP-4977 remediation plan

All,

Attached is the remediation plan for 2RP-4977. Please note the GPS on the initial C-141 is incorrect. The correct GPS is in the report. Please let me know if you have any questions or wish to discuss. Thanks and have a good day.

BRUCE BAKER

ENVIRONMENTAL TECHNICIAN SR
direct 575-393-7106 ext 1523 | Cell 432-631-6982

APACHE CORPORATION
2350 W. MARLAND BLVD
HOBBS , NM 88240

ApacheCorp.com | [LinkedIn](#) | [Facebook](#) | [Twitter](#) | [StockTwits](#) | [YouTube](#)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

WARNING EXTERNAL EMAIL: This email is from an external source. Do not click links or open attachments without positive sender verification of purpose. Never enter Username, Password or sensitive information on linked pages from this email. If you are unsure about the message, please contact the ServiceDesk for assistance.