

## Bratcher, Mike, EMNRD

---

**From:** DeAnn Grant <agrant@concho.com>  
**Sent:** Thursday, February 7, 2019 8:49 AM  
**To:** Bratcher, Mike, EMNRD; jamos@blm.gov  
**Cc:** Hamlet, Robert, EMNRD; Venegas, Victoria, EMNRD; Tucker, Shelly; dmckinne@blm.gov; Jennifer Knowlton; Ike Tavaréz; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell; DeAnn Grant  
**Subject:** [EXT] (C-141 Initial) Screwdriver 24 Federal Com #002H (30-015-42914) 01-23-2019  
**Attachments:** (C-141 Initial) Screwdriver 24 Federal Com #002H (30-015-42914) 01-23-2019.pdf; Screwdriver 24 Federal Com #002H 1-23-19 Spill Calculator.pdf

Mr. Bratcher/Mr. Amos,

Please find the attached C-141 for your consideration. Also, attached is the calculation sheet to determine the estimated release volume. The liquid lost estimate is based on the spill dimensions, estimated wet soil depth and depth of fluid in the liner. No gravel was present in this lined facility as it is a Falcon Liner. The unrecovered volume is the total amount in the pasture and the residue left behind on the liner and equipment which will be cleaned by pressure wash. The spreadsheet will calculate the total volume lost. If you have any questions or concerns please do not hesitate to contact me.

Thank you,

*DeAnn Grant*

HSE Administrative Assistant

[agrant@concho.com](mailto:agrant@concho.com)

COG Operating LLC#

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

