

Liner Inspection

Remediation Activities: Standing fluids were recovered via vac truck. A roustabout crew pressure washed the containment and equipment. Absorbent pads were used to recover excess fluids. Liner maintained integrity. Water shown on pictures is from a rain event from the previous days.



DRM5T-190806-C-1410