

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised May 08, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-005-63106

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
ROOSTER COGBURN FEE

8. Well Number
1

9. OGRID Number
14049

10. Pool name or Wildcat
CHISUM; WOLFCAMP LIME

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
MARBOB ENERGY CORPORATION

3. Address of Operator
P O BOX 227, ARTESIA, NM 88211-0227

4. Well Location

Unit Letter G : 2085 feet from the NORTH line and 1650 feet from the EAST line

Section 9 Township 11S Range 28E NMPM EDDY County NM

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3728' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: RECOMPLETION ATTEMPT ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SET CIBP @7025' & DUMP 35' CLASS H CMT ON CIBP. PERF MISS W/3 SPF @6816-22' (21 SHOTS). ACDZ W/1500 GAL NEFE 15% HCL ACID. SWAB/FLOW TEST. SET CIBP @6800' & DUMP 35' CLASS H CMT ON CIBP. PERF CANYON W/1 SPF @6436-38', 6458-60', 6536-40' (11 SHOTS). ACDZ W/2000 GAL NEFE 15% HCL ACID. SWAB/FLOW TEST. SET CIBP @6400' & DUMP 35' CLASS H CMT ON TOP OF CIBP. PERF WOLFCAMP W/1 SPF @5911-15', 5949-67', 6051-53', 6092-94' (21 SHOTS). ACDZ W/4000 GAL NEFE 15% HCL ACID. SWAB/FLOW TEST.

RECEIVED
MAR 19 2004
OCD-ARTESIA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Brian Collins TITLE ENGINEER DATE 3/19/04

Type or print name BRIAN COLLINS Telephone No. (505) 748-3303
(This space for State use)

APPROVED BY Gerry Guye TITLE Compliance Officer DATE 3.19.04
Conditions of approval, if any: