

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-71052

Release Notification and Corrective Action

OPERATOR

☐ Initial Report

☒ Final Report

Name of Company	Clayton Williams Energy, Inc.	Contact	<input type="checkbox"/> Matt Swierc, Production Supt.
Address	Six Desta Drive, #3000, Midland, TX 79705	Telephone No.	<input type="checkbox"/> (432) 682-6324
Facility Name	STATE 20B #7	Facility Type	<input type="checkbox"/> pumping oil well

Surface Owner	State of New Mexico	Mineral Owner	State of New Mexico	Lease No.	<input type="checkbox"/> B6846
---------------	---------------------	---------------	---------------------	-----------	--------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	20	17S	29E	330	North	2310	East	<input type="checkbox"/> Eddy

NATURE OF RELEASE

Type of Release	Oil & water	Volume of Release	3-5 bbls.	Volume Recovered	<input type="checkbox"/>
Source of Release	stuffing box leak	Date and Hour of Occurrence	02/23/04; 12:00 p.m.	Date and Hour of Discovery	02/23/04; 2:00 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mr. Jerry Guy, NM OCD Field Representative		
By Whom?	<input type="checkbox"/> Phillip Creech, Production Foreman	Date and Hour	<input type="checkbox"/> 02/23/24; 2:02 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

MAR - 9 2004

OCD-ARTESIA

Describe Cause of Problem and Remedial Action Taken.*

Stuffing Box leaked. Repair & replace rubbers on stuffing box.

Describe Area Affected and Cleanup Action Taken.*

Area affected: location around well head, approx. 6' L x 1' W

Clean Up Action Taken: As per Mr. Guy's instructions, utilize backhoe to spread soil on ground surface, dig down to clean soil, and turn to remediate soil so that contaminates are within guideline levels. Operation complete 3/8/04

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Matt Swierc</i>	Approved by <input type="checkbox"/> District Supervisor:		
Printed Name: Matt Swierc			
Title: Production Supt.	Approval Date:	Expiration Date:	
Date: March 8, 2004 Phone: (432) 682-6324	Conditions of Approval:	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary