

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised June 10, 2003

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.  
30-015-33282

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name  
Apollo Fee

8. Well Number  
1

9. OGRID Number  
155615

10. Pool name or Wildcat  
Loving Morrow (North) 80695

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well:  
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator  
Nadel and Gussman Permian, L.L.C.

3. Address of Operator  
601 N. Marienfeld, Suite 508 Midland, TX 79701

4. Well Location

Unit Letter \_\_\_\_\_ : 660 feet from the South line and 660 feet from the West line

Section 4 Township 23S Range 28E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
GL 3011'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☒

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SPUD WELL 3/24/2004

03/25/04

RIH w/ 10 jts (431') 48# 13 3/8" casing (welded notched collar, washed casing from 150'-170'), circulate on bottom while RU Schlumberger, pump 30 bbl gel, lead w/ 155 sx 35:65 Pos (12.6#/gal), tail in w/ 200 sx C w/ 2% gel (14.8#/gal), circulate 70 sx to surface, jet pits while WOC, dig out cellar, cut off conductor & 13 3/8", weld on A section.  
WOC for 18 hours.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Josh Fernau TITLE Staff Engineer DATE 03/26/04

Type or print name Josh Fernau E-mail address:  Telephone No. 432/682-4429

(This space for State use)

APPROVED BY FOR RECORDS ONLY TITLE  DATE APR 05 2004

Conditions of approval, if any: