UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					NMNM29268 6. If Indian, Allottee or Tribe Name		
1. Type of Well	TO MANA			8. Well Name and No. BMPIRE ABO N 4			
Oil Well Gas Well Other 2. Name of Operator Contact: KELLIE			() () () () () () () () () ()				
BPAMERICA PRODUCTION COMPANY Contact. KELLII E-Mail:			URRISH STEEN APT WEIL No. 30-015-00823-00-S1				
3a. Address	3b. Phone No. (include area code) Ph. 505.394 1649			10. Field and Pool, or Exploratory			
EUNICE, NM 88231	Fx: 505.394.1624			11. County or Parish, and State			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 8 T18S R27E SENE 2260FNL 400FEL			98	97.47.0	EDDY COUNTY		te
12. CHECK APP	ROPRIATE BOX(ES) TO	INDICATE N	JATURE O	F NOTICE, RI	EPORT, OR OTHE	R DA	ГА
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	☐ Acidize	□ Deepe	n	□ Product	☐ Production (Start/Resume) ☐ Water Shut-		
_	☐ Alter Casing	□ Fractu	re Treat	□ Reclama	Reclamation		Vell Integrity
☐ Subsequent Report			Construction	-	Recomplete		ther
☐ Final Abandonment Notice	☐ Change Plans	_	Plug and Abandon		☐ Temporarily Abandon		
	Convert to Injection	□ Plug F	łack	□ Water D	□ Water Disposal		
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Aidetermined that the site is ready for 1 TD: 9580' PBD: 9579' CIBF MIRUPU. NDWH. NUBOP. PU 2-3/8" WS & RIH. TAG CLOAD HOLE W/9.5# KCL MLPUH. SPOT 25 SXS CMT F/2 PUH AND SPOT 25 SXS CMT POH W/TBG. RUWL & PERF CSG @ 2820 RIH TO 780'. PMP 25 SXS CPUH TO 60'. PMP 10 SXS CCUT OFF WH. INSTALL DR'	operations. If the operation rebandonment Notices shall be fill inal inspection.) 2: 5138' TOC: 2920' IBP @ 5138'. PMP 25' CID. PRESS TEST TO 300 2945-2845' ACROSS TOF ACROSS TOF ACROSS 8-5/8" CSG SID. TRY TO CIRC KCL BE IMT ACROSS QUEEN (10 MT F/60' TO SURF. WOLLD WOLLD MARKER W/LECT	MT ON TOP OF GLORIET HOE @3089'. TWEEN 8-5/8" 00' PLUG). WCC 24 HRS. TAG	completion or a quirements, inc AF GE F CIBP. SF TA. (100' P (100' PLUG & 5-1/2" CS DC. TAG & G & RECOR	PROVAL SENERAL REPECIAL STILL PLUG). WOC. TO WOC. TAG BG. PMP CMT RECORD TOC.	new interval, a Form 316 n, have been completed, UBJECT TO QUIREMENTS PULATIONS AT TAG & RECORD TO & RECORD TOC. TO SURF. RDWL.	0-4 sha and the AND TACI	Il be filed once operator has
14. I hereby certify that the foregoing is	Electronic Submission # For BPAMERICA P	RODUCTION CO	OMPANY, se	nt to the Carlsb	ad		
Name (Printed/Typed) KELLIE D	cessing by LINI	DA ASKWIG	on 06/22/2004 (0	PRESENTATIVE			
	c®		,				
Signature (Electronic	Submission)			3/2004			
	THIS SPACE FO	OR FEDERAL	OR STAT	E OFFICE U	SE		
Approved By LES BABYAK			TitlePETRO	IEPETROLEUM ENGINEER			Date 07/02/2
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Carls			<u>1</u>	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations a	a crime for any per s to any matter wit	son knowingly hin its jurisdict	and willfully to m	ake to any department o	r agency	y of the United

WELLBORE SCHEMATIC

Thansaction # 32137

10 SX CMT 60' TO SURF.

25 sx cmt across QUEEN 780'-680' -- 100' PLUG

8-5/8" casing @ 3089' Cmt Circulated to surface EMPIRE ABO UNIT N-4 2260' FNL & 400' FEL SEC 8, T - 18S, RANGE 27E EDDY COUNTY, NM API 30-015-00823 GR 3501' KB: 11'

TOC @ 2920' IN 5 1/2"

25 SX CMT ACROSS CSG SHOE 100' CMT PLUG

TOP OR GLORIETA 2795' 25 SX CMT 2845'-2945'

CIBP @ 5138'

PERFORATIONS 5176'-5186'

CIBP @ 5235' PERFORATION 5260'-5406'

CIBP @ 9360'

PERFORATION 9505'-9555'

TD @ 9580"

PBD @ 9579'

5-1/2" csg @ 9580" TOC @ 2920'