N.M. Oil Cons. DIV-Dist. 2 1301 W. Grand Avenue

*	Artesia, NM 88210	FORM APPROVED
Form 3160-5 UNITED STA	ATES	Budget Bureau No. 1004-0135
(June 1990) DEPARTMENT OF THE INTERIOR		Expires: March 31, 1993
BUREAU OF LAND M		5. Lease Designation and Serial No.
		NM-12211
SUNDRY NOTICES AND RE	EPORTS ON WELLS	6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to drill or	to deepen or reentry to a different reservoir.	
Use "APPLICATION FOR PERI		
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
. Type of Well		
Oil Gas	RECEIVED	
Well Well Other		8. Well Name and No.
Name of Operator	AUG 0 5 2004	T-Bone Federal #1
CHI OPERATING, INC.	OGD-ARTESIA	9. API Well No. 30-015-32122
3. Address and Telephone No. P.O. BOX 1799 MIDLAND, TEXAS 79702		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, T., R., M., or Survey Description)		Undsg Shugart Morrow
660' FNL & 1980' FWL		11. County or Parish, State
Sec 33-T18S-R31E		EDDY
	INDICATE NATURE OF NOTICE, REPORT,	OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
_A_A	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water
		(Note: Report results of multiple completion on Well
		Completion or Recompletion Report and Log form)
	pertinet details, and give pertinet dates, including estimated date of st and true vertical depths for all markders and zones pertinent to this w	- · · · ·
1 RU DD PU. POOH w/RBP, pacl	•	
2 Set CIBP at 11,740' (above Moi		
3 Set CIRD at 0060' (above Molfe	camp) and spot35' of cement on top.	
3 SEL CIDE AL BAOO (ADOVE MONE	IOU (ECTIMATER - PLANTS BUIL FORC	POLATE TO DETERMINE DEAT
4 Cut 5-1/2" casing at 2000' & PO		formal to scientifica and
4 Cut 5-1/2" casing at 2000' & PO 5 Spot 150' cement plug half-in at	nd half-out at 2000'. Tag.	foull to Scientific and
4 Cut 5-1/2" casing at 2000' & PO 5 Spot 150' cement plug half-in au 6 100' cement plug @ <i>500</i> 0ーゆ	nd half-out at 2000'. Tag. のの、TAG (DV TOOL@ 5036′)	toust to beleficiate and
4 Cut 5-1/2" casing at 2000' & PO 5 Spot 150' cement plug half-in at 6 100' cement plug © 5000-b 7 100' cement plug f/3550-3650' (nd half-out at 2000'. Tag. <i>600'</i> . TA& (DV T00L@ 5036') 1 3-3/8 " casing shoe).\$ <i>5</i> /8" TA&	
4 Cut 5-1/2" casing at 2000' & PO 5 Spot 150' cement plug half-in at 6 100' cement plug @ 5000-6 7 100' cement plug f/3550-3650' (Install dry hole marker & reclain	nd half-out at 2000'. Tag. <i>600'</i> . TA& (DV T00L@ 5036') 1 3-3/8 " casing shoe).\$ <i>5</i> /8" TA&	CMT PLUG F/590-690'.
4 Cut 5-1/2" casing at 2000' & PO 5 Spot 150' cement plug half-in at 6 100' cement plug 5000 -6 7 100' cement plug f/3550-3650' (Install dry hole marker & reclain	nd half-out at 2000'. Tag. 600'. TAG (DV TOOL@ 5036') 13-3/8" casing shoe).95/8" TAG n location.	CAIT PLUG F/590-690'
4 Cut 5-1/2" casing at 2000' & PO 5 Spot 150' cement plug half-in at 6 100' cement plug 5000 -6 7 100' cement plug f/3550-3650' (Install dry hole marker & reclain	nd half-out at 2000'. Tag. <i>600'</i> . TA& (DV T00L@ 5036') 1 3-3/8 " casing shoe).\$ <i>5</i> /8" TA&	
4 Cut 5-1/2" casing at 2000' & PO 5 Spot 150' cement plug half-in at 6 100' cement plug @ 5000 b 7 100' cement plug f/3550-3650' (Install dry hole marker & reclain 14. I hereby count that the foresoing it true and correct Signed	nd half-out at 2000'. Tag. 600'. TAG (DV TOOL@ 5036') 13-3/8" casing shoe).\$\$/6" TAG- n location. Title Regulatory Clerk	CMT PLUG F/590-690', 1336" CASING SHOG) SURFACE PLUG 6/17/04
4 Cut 5-1/2" casing at 2000' & PO 5 Spot 150' cement plug half-in at 6 100' cement plug @ 5000	nd half-out at 2000'. Tag. 600'. TAG (DV TOOL@ 5036') 13-3/8" casing shoe).\$5/8" TAG 8. 100' n location. Title Regulatory Clerk	CAIT PLUG F/590-690'
4 Cut 5-1/2" casing at 2000' & PO 5 Spot 150' cement plug half-in at 6 100' cement plug @ 5000-6 7 100' cement plug f/3550-3650' (Install dry hole marker & reclain 14. I hereby certify that the foregoing it true and correct Signed (This space for Federal or State office use) Approved by (ORIG. SGD.) ALEXIS C. SWOT	nd half-out at 2000'. Tag. 600'. TAG (DV TOOL@ 5036') 13-3/8" casing shoe).\$5/8" TAG 8. 100' n location. Title Regulatory Clerk	CMT PLUG F/590-690', 1336" CASING SHOG) SURFACE PLUG 6/17/04
4 Cut 5-1/2" casing at 2000' & PO 5 Spot 150' cement plug half-in at 6 100' cement plug @ 5000	nd half-out at 2000'. Tag. 600'. TAG (DV TOOL@ 5036') 13-3/8" casing shoe).\$5/8" TAG 8. 100' n location. Title Regulatory Clerk	CMT PLUG F/590-690', 1336" CASING SHOG) SURFACE PLUG 6/17/04

APPROVAL SUBJECT TO SECOND SPECIAL STIPULATIONS ATTACHED



