Form 3160-5 (September 2001)

Oil Cons.

FORM APPROVED OMB No. 1004-0135 Expires: January 31, 2004

5. Lease Serial No.

UNITED STATES N.M. DIV-Dist. 2
DEPARTMENT OF THE INTERIOR W. Grand Avenue
BUREAU OF LAND MANAGEMENT
Artesia, NM 88210
SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

LC 060325 6. If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such proposals.							
SUBMIT IN TRIPLICATE - Other instructions on re					or CA/Agreement, Name and/or No.		
☑ Oil Well ☐ Gas Well ☐ Other		ANS 16 17 18 19 20 3		8. Well Name and No.			
2. Name of Operator		A Pos		Tract 9 Well 14			
J. Cleo Thompson				9. API Well No.			
		50. Phone No. (include aneaschae)		30-015-04082			
P.O. Box 237 Loco Hills, NM 88255 (505) 6		7-2396 R	2396 RECEIVED 10 10. FI		Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T, R., M., or Survey Description)		000	OCD - ARTESIA		Grayburg San Andreas		
Unit Letter I of Sec. 4, T17S, R30E NMP 1980 5 - 660 25					11. County or Parish, State Eddy, NM		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION TYPE			TYPE OF ACTION	PE OF ACTION			
Notice of Intent	☐ Acidize ☐ Deepen ☐ Alter Casing ☐ Fractur		Production (Start/	Resume)		· Shut-Off	
E71 Subarana Paras		onstruction		5		Re-enter	
Subsequent Report		d Abandoi	=	•	• Other	T-A Well	
Final Abandonment Notice	Convert to Injection Plug Ba		Water Disposal	iidon	+	1-A WOII	
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 31 testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been complete determined that the site is ready for final inspection.) 1. Rig up on 11/13/00. 2. Pick up 6 1/4 bit 6 - 3 1/2 Drill collars G.I.H. Tag fill @ 2600'. 3. C.O. from 2600' dwn to 3122' (T.D.) Circulate hole clean C.O.H. 4. Lay dwn tools. 5. Pick up PKR G.I.H. Set @ 2750' test to 500#'s for 15 mins, ok. 6. C.O.H. lay PKR dwn, pick up Production string G.I.H. w/94 jts. 2 3/8 tubing. 7. Run rods and pump. FEB 1 2 2003 ALEXIS C. SWOBODA PETROLEUM ENGINEE					CORD		
14. I hereby certify that the foregoin Name (PrintedlTyped) Amador Pando Jr.	g is true and correct	Title	Production Foreman				
J.f. M. J. Ol	THIS SPACE FOR FEDE	Date	11/21/00				
Approved by (Signature)			Name (Printed/Typed) Title				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office			ate	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.