Submit 3 Copies To Appropriate District Office	State of]			Form C-103			
District I . 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources				Revised March 25, 1999 WELL API NO.		
District II					30-015-04004		
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION District III 1220 South St. Francis Dr.				5. Indicate Ty	5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410					STATE FEE XX		
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505					6. State Oil & Gas Lease No. LC 063926		
SUNDRY NOT	TCES AND REPORTS OF	WELLS		7. Lease Nam	e or Unit Agreer	nent Name:	
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEP	EN OR PLUC	BACKTO 167	/>			
PROPOSALS.)	_ATION FOR PERMIT" (FORM	C-101) FOR	SUCH	SWSTO			
1. Type of Well: Oil Well Gas Well C	T 0.1	1 83,	" X	103			
Oil Well Gas Well 2. Name of Operator	Other W.I.W	1 /20	5003	Tract 5			
J. Cleo Thompson		56	RECEIVER	Tract 5 8. Well No. 8 Pool name			
3. Address of Operator		/ co	000 - 477	9. Pool name	or Wildcat		
P.O. BOX 237 LOCO	Hills, N.M. 88	3255	<u>.</u>	Grayburg	- San And	reas	
4. Well Location	·	,	₹€08.05.82]				
Unit Letter F	: 1980 feet from the	N	line and	1980 feet	from the W	line	
	IOOT HOIL UIV		inic and	ica	nom me	inic	
Section 35	Township	16S	Range 30E	NMPM	County	y Eddy	
	10. Elevation (Show w	hether DR	, RKB, RT, GR, e	etc.)			
11 Check	Appropriate Box to Inc	dicata Na	tura of Nation	Donort or Oth	on Doto		
NOTICE OF IN	NTENTION TO:	uicate iva		SEQUENT F			
PERFORM REMEDIAL WORK			REMEDIAL WO		ALTERING		
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DE	RILLING OPNS.	PLUG AND ABANDONN	AENT.	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST /	AND £	k ABANDONN	MENT	
OTHER:			OTHER: Dark	1 1		₽	
12. Describe proposed or complete starting any proposed work). S	ed operations. (Clearly sta SEE RULE 1103. For Mul	te all perti	nent details, and	back on I give pertinent da wellbore diagram	es, including est	imated date of	
recompilation.							
On 11-17-00 work bega	n as follows;						
 Unseat Pkr. Came o Replace old wellhe 							
3. Pick up 3 7/8 bit		n out	dwn to 32	00 г.о.н.			
4. Pick up new $4 1/2$	tension pkr. Go	in ho	ole dwn to	2690' cir	culate pk	r fluid	
Set Pkr. Test csg.	520# for 30 mi	ln. A-0	OK Witness	ed by Cath	y Queen W	/BLM.	
Pack well off.	• • · · · ·						
5. Hook up injection 6. Began injecting 11		25 hh1	le nor day				
Bottom of liner 31		23 001	ra her nal	•			
Top of liner 2632'	<i>31</i> °						
7" csg. @ 2875'							
I hereby certify that the information	ahove is true and comple	te to the he	et of my knowled	dge and balisf		·	
	, and and comple	w wait oc	at of my knowic	uge and venel.			
SIGNATURE / AND A	/2 .	TITLE_P	coduction	Foreman	DATE2	-7-02	
	Pando Jr.				Telephone No.	505-677-2	
(This space for State use)						239	
APPPROVED BY	n	ΓITLE			DATE		
Conditions of approval if any:		IIILE			DATE		

