

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.	30.015.22009
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Lease Name or Unit Agreement Name Empire Abo Unit "H"
2. Name of Operator BP America Production Company	8. Well No. 272
3. Address of Operator P.O. Box 1089 Eunice, NM 88231	9. Pool name or Wildcat Empire Abo
4. Well Location Unit Letter <u>0</u> ; <u>330</u> Feet From The <u>S</u> Line and <u>2481</u> Feet From The <u>E</u> Line Section <u>32</u> Township <u>17S</u> Range <u>28E</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3672 RDB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Workover ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6370' PBD: 6261' PKR: 6121' PERFS: 6164-6166' (OLD), 5714-6120' (NEW)

02.10.03: MIRUPU. Drop SV. RWL & pmp 30 bbls to load tbq. Perf tbq above SN @ 6105. POH.

02.11.03: NDWH. NUBOP. Unset pkr. POH w/prod tbq. RIH w/bit & scraper.

02.12.03: Tag @ 6189'. POH. RIH w/RBP & pkr. Set RBP @ 5663'. Pull up & set pkr @ 5632'. Load & test RBP & csg to 500#. Held good. Unset pkr. PU swab & swab well.

02.13.03: Unset & POH w/RBP & pkr. RIH w/perf guns & perf well f/5714-18', 5724-26', 5741-46', 5770-78', 5796-98', 5836-41', 5846-58', 5962-80', 6035-39', 6076-86', & 6104-20'. RDWL.

02.14.03: RIH w/RBP & pkr. Set BP @ 6130'. Pull up 1 jt. RU acid trucks & spot 10 bbls (OVER)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Sr. Administrative Assistant DATE 03.06.03
TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505.394.1649

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

**Empire Abo Unit H-272
Workover Operations**

02.14.03 cont:

15% HCL NEFE. PU & set pkr @ 5603'. Pmp 109 bbls 15% HCL NEFE followed by 300 ball sealers. RD acid trucks.

02.17.03:

Unset pkr & POH w/pkr & BP. RIH w/prod assy. Set 2-3/8" tbg @ 6111'. NDBOP. NUWH. Swab well.

02.19.03:

RTP. In 24 hrs. Pmped 1 BO, 0 BW, 160 MCF.