Form 3160-5 (November 1983) (Formerly 9-331)

## Oil Cons. 1301 W. Goand Av **UNITED STATES**

Budget Bureau No. 1004-0135 Expires August 31, 1985

DEPARTMENT OF THE INTERIOR SIA, NIM 88210 5. LEASE DESIGNATION AND SERIAL NO. LC-029418-A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals.) ī 7. UNIT AGREEMENT NAME OIL GAS **OTHER** Skelly Unit WELL. WELL 2. NAME OF OPERATOR 8. WELL NAME AND NO. The Wiser Oil Company 148 3. ADDRESS OF OPERATOR 9. API WELL NO. P.O. Box 2568 Hobbs, New Mexico 88241 30-015-22530 LOCATION OF WELL (Report location clearly and in accordance with any State requirements CEIVED 10. FIELD AND POOL, OR WILDCAT See also space 17 below.) Grayburg Jackson Fren 7-Rivers-ON-GB-SA OCD - ARTESIA At surface 11. SEC., T., R., M., OR BLK. AND 560' FSL & 560' FEL SURVEY OR AREA Unit P Sec. 14-T17S-R31E 2324261 14. PERMIT NO 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 12. COUNTY OR PARISH 13. STATE 3895' GR Eddy County NM 16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: TEST WATER SHUT OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING SHOOT OR ACIDIZE ABANDON\* SHOOTING OR ACIDIZING ABANDONMENT \* **REPAIR WELL** CHANGE PLANS (Other) (Note: Report results of multiple completion on Well (Other) Plug and Abandon Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) Wiser requests approval to Plug and Abandon the well by the procedure listed below. Surface Casing: 8-5/8" set @ 692' Production Casing: 5-1/2" set @ 3729' Perfs: 3342'-3628' CIBP @ 3310' Spot 50' plug on CIBP @ 3310'. Tag coment plug. Circulate abandonment mud. Spot-50 cement plug @ 1750' to 1760' 1850 ' Tag cement plug Spot 50' coment plug @ 700' to 650' - 750 APPROVAL SUBJECT TO GENERAL REQUIREMENTS AND Tag plug Spot 50' cement plug to surface SPECIAL STIPULATIONS ATTACHED Install dry hole marker. Clean location. 18. I hereby certify that the foregoing is true and correct. **SIGNED** Prod. Supt DATE April 1, 2003 (This space for Federal or State office use)

\*See Instruction On Reverse Side

PETROLEUM ENGINEER

APPROVED BY (ORIG. SGD.) ALEXÍS C. SWOBODA

CONDITIONS OF APPROVAL, IF ANY: