

N.M. Oil Cons. DIV-Dist. 2  
1301 W. Grand Avenue  
Artesia, NM 88210  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

5. Lease Designation and Serial No.  
Lc-061497

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.  
Gulf Federal #1

9. API Well No.  
30015-25144

10. Field and Pool, or Exploratory Area  
Brushy Draw Del.

11. County or Parish, State  
Eddy NM

**SUNDRY NOTICES AND REPORTS ON WELLS**  
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well  
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator  
Claco Oil Company

3. Address and Telephone No.  
13 Havenhill Rd. Artesia, NM 88210 (505) 457-2286

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
Sec13, T26S,R29E, Unit leatter

RECEIVED

SEP 17 2004

OOB-ARTESIA

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other \_\_\_\_\_  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Notify BLM 24 hrs before starting Plugging

1. POH w/ rods & tubing set 5 1/2 CIBP @ 5200' w/ 35' cmt on top
2. RIH circulate well W/ mud Spot 100' plug @ 4600)
3. Pull stretch on 5 1/2 if free below 3200 cut & pull if not spot 100' Plug @ 3200 ( 8 5/8 shoe @ 33158 ) woc tag
4. Spot 100' plug 50' in & 50' out cut woc tag
5. Cut & pull 8 5/8 @ 1000' + or -
6. RIH spot 100' plug 50' in & out woc tag
7. Spot 100' plug @ 400' ( 13 3/8 shoe @ 344' ) woc tag
8. Spot cmt. 60' to surface
9. Cut off well head install dry hole marker

APPROVAL SUBJECT TO  
GENERAL REQUIREMENTS AND  
SPECIAL STIPULATIONS ATTACHED

14. I hereby certify that the foregoing is true and correct

Signed Walter Burch  
(This space for Federal or State office use)

Title Agent

Date 9/13/04  
SEP 15 2004

Approved by (ORIG. SGD.) ALEXIS C. SWOBODA  
Conditions of approval, if any:

Title PETROLEUM ENGINEER

Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side