

Submit 3 Copies to Appropriate District Office  
 District I  
 P. O. Box 1988, Hobbs, NM 88240  
 District II  
 P. O. Drawer DD, Artesia, NM 88210  
 District III  
 1000 Rio Brazos Rd. Aztec, NM 87410

State of New Mexico  
 Energy, Minerals and Natural Resources  
**OIL CONSERVATION DIVISION**  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

**RECEIVED**

SEP 20 2004

**DOB-ARTESIA**

Form C-103  
 March 4, 2004

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		Well API NO. <b>30-015-33295</b>
1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Indicate Type of Lease <input checked="" type="checkbox"/> State <input type="checkbox"/> Fee
2. Name of Operator <b>DEVON LOUISIANA CORPORATION</b>		6. State Oil & gas Lease No.
3. Address and Telephone No. <b>20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-228-8209</b>		7. Lease Name or Unit Agreement Name <b>Eddy FT State Com</b>
4. Well Location Unit Letter <u>I</u> <u>1600</u> feet from the <u>SOUTH</u> line and <u>1200</u> feet from the <u>EAST</u> line Section <u>26</u> <u>20S</u> Township <u>27E</u> Range <u>NMPM</u> <u>Eddy</u> County		8. Well Number <b>4</b>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3324		9. Ogrid Number <b>169355</b>
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		10. Pool Name or Wildcat <b>Burton Flat: Morrow, East</b>

<b>NOTICE OF INTENTION TO:</b> <input type="checkbox"/> PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> Other _____	<input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> MULTIPLE COMPLETION	<b>SUBSEQUENT REPORT OF:</b> <input type="checkbox"/> REMEDIAL WORK <input checked="" type="checkbox"/> COMMENCE DRILLING OPN <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER _____	<input type="checkbox"/> ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT
---	--	--	---

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram or proposed completion or recompletion. If a pit or below-grade tank is involved in the operation, complete the reverse side of this form.

07/13/04 Spud 17 1/2" hole  
 07/14/04 Ran 11 jts 13 3/8" 48# H40 ST&C csg to 517'. Cmt lead w/ 250 sx 35:65 Poz & tail w/ 250 sx CI C. Circ 36 sx to pit. WOC 18 hrs. Test csg to 1000# - Held.  
 07/17/04 TD 12 1/4" hole @ 2426'. Ran 55 jts 9 5/8" 36# LT&C csg @ 2425'. Cmt lead w/ 250 sx Thixotropic, 2nd lead w/600 sx 35:65 Pozmix & tail w/ 250 sx Class C. Ran temp survey, TOC @ 1300'.  
 07/18/04 RIH w/ 1", tag cmt @ 770'. Set 100 sx cmt plug @ 806'. WOC. RIH w/ 1", tag @ 812', pull up to 806'-pump 100 sx Class C. WOC TIH w/ 1", tag @ 667'. Pump 100 sx Class C @ 660'. WOC. TIH w/1", tag @ 425', pump 150 sx Class C. Circ 14 sx to pit. WOC 24 hrs.  
 07/20/04 Test 9 5/8" csg to 1000 psi--held.  
 08/09/04 TD 8 3/4" hole @ 11,427'. Circ & cond hole.  
 08/12/04 Ran 273 jts 5 1/2" 17# P110 LT&C csg @ 11427'. Cmt 1st stg lead w/ 800 sx Class C, open DV tool, circ 585 sx off tool to pit. Cmt stg 2 lead w/ 1150 sx Class H, circ 633 sx off tool to pit. Cmt 3rd stg w/ 1875 sx 60:40 Class C, circ 854 sx to surface.  
 08/14/04 Released rig.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Linda Guthrie TITLE Regulatory Specialist DATE 9/17/2004  
 Type or Print name Linda Guthrie E-mail Address: linda.guthrie@dvn.com Telephone No. 405-228-8209  
 (This space for State use)

APPROVED BY FOR RECORDS ONLY DATE SEP 21 2004  
 Conditions of approval, if any: