

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
N.M. Oil Cons. DIV-Dist. 2
1301 W. Grand Avenue
Alamosa, NM 88210

FORM APPROVED
Budget Bureau No. 1004-0135
Expires March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other _____

RECEIVED

2. Name of Operator

DEVON ENERGY PRODUCTION COMPANY, LP.

OCT - 1 2004

3. Address and Telephone No.

20 NORTH BROADWAY, SUITE 1500, OKLAHOMA CITY, OKLAHOMA 73102 (405) 552-4615

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FNL, 660' FWL, Sec 17-T18S-R31E, Unit E

5. Lease Designation and Serial No.

LC-029393-B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

W. Shugart 17 Fed #1

9. API Well No.

30-015-31505

10. Field and Pool, or Exploratory Area

Shugart Bone Spring North

11. County or Parish, State

Eddy County, NM

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water


(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. POOH with 2-7/8" production string.
2. Set CIBP @ 3786'. Tagged plug. Capped w/ 25 sx Cl "C" cement from 3539' to 3786'
3. Displace hole w/ 9.5# mud.
4. Set 25 sx cement plug from 2715' to 2915'. TOC tagged at 2715'
5. Shot sqz holes at 843'. Pumped 40 sxs cement. Sqzd & set cement plug in/out on 5-1/2" casing from 577' to 843'. Tagged at 577'.
6. Shot sqz holes at 60'. Set cement plug in/out on 5-1/2" casing from 60' to surface.
7. Cut off casings 3' below ground level.
8. Install dry hole marker.
9. Well plugged and abandoned on 9/23/2004.

Note: Cement class "C" at 14.8 ppg with a yield of 1.32 cu. ft/sx

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.



14. I hereby certify that the foregoing is true and correct

Signed Ronnie Slack Title Engineering Technician

Date 9/23/04

(This space for Federal or State office use)

Approved by _____

Title _____

Date _____

Conditions of approval, if any:

DEVON ENERGY PRODUCTION COMPANY LP

Well Name: West Shugart 17 Federal #1		Field: Shugart Bone Spring North	
Location: 1980' FNL & 660' FWL Sec 17-18S-31E		County: Eddy	State: NM
Elevation: 3643' GR		Spud Date: 3/13/01	Compl Date: 4/20/01
API#: 30-015-31505	Prepared by: Ronnie Slack	Date: 9/2/04	Rev:

