Submit 3 Copies To Appropriate District Office	State of New Me	xico	Form C-103	
District I	Energy, Minerals and Natur	ral Resources	May 27, 2004	
1625 N. French Dr., Hobbs, NM 88240		WE.	LL API NO.	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-015-33289 ndicate Type of Lease	
District III	1220 South St. Fran	icis Dr.	STATE X FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87	7505 6. S	State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM			B-8096	
87505 SUNDRY NOTI	CES AND REPORTS ON WELLS	7. I	Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PLU	JG BACK TO A		
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	CATION FOR PERMIT" (FORM C-101) FO	OR SUCH	TDC STATE SECTION 8	
1. Type of Well: Oil Well X Gas Well Other			8. Well Number 2	
2. Name of Operator			OGRID Number 23032	
THRESHOLD DEVELOPMENT COMPANY			D. I. Will.	
3. Address of Operator 777 TAYLOR STREET, PENTHOUSE II-D, FORT WORTH, TX 76102			Pool name or Wildcat Iman-Yates-SR-Q-GB-SA, East	
4. Well Location	OUSE II-D, FORT WORTH, TA	10102	Ilian-Tatts-SK-Q-GD-SA, East	
	feet from the North	line and 990	feet from the West line	
Section 8	Township 19s	Range 29E	NMPM Eddy County	
Section	11. Elevation (Show whether DR,		- Nivii ivi Eddy County	
3378' GR				
Pit or Below-grade Tank Application or Closure				
Pit type Depth to Groundwater NADistance from nearest fresh water well + 2 mi Distance from nearest surface water + 2 mi				
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO				
I			QUENT REPORT OF:	
PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN		X ALTERING CASING GOPNS. PANDA		
TEMPORARILY ABANDON DULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT JOB		
FOLE OR ALTER CASING	MOLTIFLE COMPL	CASING/CEIVIENT JOB		
OTHER:		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of				
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
9/7/04 - MIRU WSU. Unbridle pump jack. Release rods off pump. TOOH w/rods, LD on ground. NU BOPS. Release				
TA. TOOH w/tubing. LD tubing pump. PU RBP. Set with the @ 2,577'. TOOH. PU ArrowSet 1X packer. Set packer,				
Test RBP to 2,000 psi. Spot 200# sand on RBP. TOOH w/packer. RU lubricator and wireline. Tie into open hole logs				
with GR strip. Peforate Penrose 2,177' - 2,182', 2,192' - 2,197'. 20 shots total. TIH, Set packer @ 2143'.				
0/8/04 _ PH Acidizers Sr	not 3 bbls 15% IC HCI @ 2 197	Pick up to 2 1/3' revers	se tha set nacker. Acidize Penrose	
9/8/04 – RU Acidizers. Spot 3 bbls 15% IC HCI @ 2,197'. Pick up to 2,143', reverse tbg, set packer. Acidize Penrose w/2,000 gallons 15% Hcl carrying 40 7/8" RCN ball sealers. Breakdown @ 2,000 psi. ballout to 4,102 psi. Swab. SIFN				
	• 5	•	•	
9/9/04 – Swab, SIFN				
9/10/04 – Released packer	· circulated casing clean, TOOH.	Renlaced nacker, TIH.	set @ 1,518'. ND BOPs. NU wellhead.	
RDD WSU. SI	, on culated casing cicam 10011.	replaced packer, 1111,		
			RECEIVED	
	CONTINUED ON	NEXT PAGE:	OCT 2 9 2004	
			OOD:ARTESIA	
I hereby certify that the information	shove is true and complete to the h	est of my knowledge and	belief. I further certify that any pit or below-	
			(attached) alternative OCD-approved plan .	
~· \.	2	-	D. 1777 40 (04 (04	
SIGNATURE unda	TITLE_	Regulatory Analyst	DATE10/21/04	
Type or print name Linda Bro	own E-mail address: Ibro	own@thresholddevelopm	nent.com_Telephone No. 817-870-1483	
For State Use Only				
N OV 0 7 200				
APPROVED BY: FOR				
**				

THRESHOLD DEVELOPMENT COMPANY TDC 8 STATE #2 SECTION 8-19S-R28E EDDY COUNTY, NEW MEXICO

SUNDRY NOTICE CONTINUED:

9/18/04 - 3 frac tanks loaded w/59,300 gals 2% KCL water. MIRU frac equip. Gel tanks, perform QC tests. RU frac lines. Frac Penrose sand w/1,407 bbls 20# borate crosslinked quar gel carrying 123,630 lbs of 16/30 Brady Sand. Flush w/base gel. Flow back on forced closure @ ½ bpm. Closure obtained in 14 minutes @ 668 psi. Shut in wellhead. RD Frac equip. Open well on ¼" choke @ 1 bpm to steel tank. Flow broken gel for 1 hr. Flow back 207 bbls until flow is minimal. RU WSU. SIFW

9/20/04 - Open to tankRU reverse unit. Load thg. Unseat pkr. TOOH. PU retrieving tool. TIH, wash ~ 100' sand, retrieve RBP. LD RBP. TIH, wash sand to PBTD @ 3,060'. TOOH, LD excess thg. SIFN

9/21/04 - Blow down with no fluid. TOOH. Pu tubing pump w/6' perf sub. Run tbg string. ND BOPs. Run rod string Load tbg, long stroke to 400 psi. Hang off. RD WSU. Start pump.

Linda Brown Regulatory Analyst