

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

ORIGINAL

30-015-28011

Release Notification and Corrective Action

n MLB0432755192

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Devon Energy Production Co. LP	Contact: Jennifer Van Curen
Address: PO Box 250; Artesia, NM 88211	Telephone No.: 505-748-0160
Facility Name: Old Ranch Canyon 7 Fed 1	Facility Type: Battery

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter B	Section 7	Township 22S	Range 24E	Feet from the 660	North/South Line North	Feet from the 1930	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Water	Volume of Release: 290	Volume Recovered: 260
Source of Release: Victaulic connection on 6" water line	Date and Hour of Occurrence 11/10/04: 4:30 am	Date and Hour of Discovery 11/10/04: 4:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Joe Huber	Date and Hour: 11/10/04: 7:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED

NOV 17 2004

OCD-ARTESIA

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Victaulic connection on 6" water line failed. Spilled 250 bbls PW inside dike with 40 bbls leaking thru dike and traveling 300' off location. Shut off flow. Vacuumed up all contained and puddled water.

Describe Area Affected and Cleanup Action Taken.*

Inspection of connection indicated pipe had been subject to movement or vibration wearing away at clamp surfaces. Plan to cement new pipe and coupling in place to prevent movement. Waiting on further clean-up recommendations from the BLM / OCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jennifer Van Curen	Approved by District Supervisor:	
Title: Production Field Tech	Approval Date:	Expiration Date:
E-mail Address: Jennifer.vancuren@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/15/04	Phone: 748-0160	

* Attach Additional Sheets If Necessary