

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised May 08, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-005-63111
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-8385
7. Lease Name or Unit Agreement Name STATE CF
8. Well Number 11
9. OGRID Number 14049
10. Pool name or Wildcat CHISUM; QUEEN

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator MARBOB ENERGY CORPORATION	
3. Address of Operator PO BOX 227, ARTESIA, NM 88211-0227	
4. Well Location Unit Letter <u>F</u> : <u>1650</u> feet from the <u>NORTH</u> line and <u>1650</u> feet from the <u>WEST</u> line Section <u>12</u> Township <u>11S</u> Range <u>27E</u> NMPM County <u>CHAVES</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3739' GL	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

PLUG & ABANDON AS FOLLOWS:

1. RIH OPEN ENDED TO 6200' +/- & CIRC WELL FULL OF 9 PPG BW CONTAINING 25 PPB SALT GEL (130 BBLS W/ TBG IN HOLE).
2. PULL UP TO 4900' & SPOT 25 SX CLASS "C" NEAT FROM 4900' TO 4646'. (ABO)
3. PULL UP TO 2000' & SPOT 25 SX CLASS "C" NEAT FROM 2000' TO 1746'. (SAN ANDRES)
4. PULL UP TO 1500' & SPOT 60 SX CLASS "C" W/ 2% CACL2 FROM 1500' TO 950'. (8 5/8" SHOE & QUEEN PERFS). PULL UP TO 500' & WOC +/- 2 HRS. TAG PLUG. IF NOT 950' OR SHALLOWER, RE-SPOT PLUG, WAIT 2 HRS & TAG.
5. PULL UP TO 60' & SPOT 10 SX CLASS "C" SURFACE PLUG AFTER REMOVING WELLHEAD/ TRIMMING CASING BELOW SURFACE.
6. AFTER WAITING 24 HRS, FILL TO SURFACE W/ CMT & INSTALL DRY HOLE MARKER.

NOTE: ALREADY HAVE CIBP @ 6320' + 35' CEMENT IN PLACE.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Diana J. Cannon TITLE PRODUCTION ANALYST DATE 1/10/05

Type or print name DIANA J. CANNON

Telephone No. (505) 748-3303

(This space for State use)

APPROVED BY Mike Bentler TITLE Compliance Officer DATE 1/19/05
Conditions of approval, if any: Contact NMOC Dist II 24 hours prior to commencement of operations