Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources			Form C-103
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals	s and Natural Resource	es WELL API	May 27, 2004 NO.
District II	OIL CONSER	VATION DIVISIO	J	30-015-21529
District III	ct III 1220 South St. Francis Dr		5. Indicate STAT	Γype of Lease ΓΕ X FEE □
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa F	e, NM 87505		& Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			E-5230	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Na BIG EDDY	7. Lease Name or Unit Agreement Name BIG EDDY UNIT	
1. Type of Well: Oil Well	Gas Well X Other		8. Well Nur	mber 44
2. Name of Operator	i D i C-	RECEIVED	9. OGRID 1	Number 001801
3. Address of Operator P. O. Box	rises Production Co.	JAN 2 8 2005	10 Pool na	me or Wildcat
Midland,	TX 79702	UCU-AHTESIA		CLIFFS (MORROW) S. GAS
4. Well Location				0222 0 (0.001010 0.0) 0.010
		NORTH line a		et from the <u>EAST</u> line
Section 16	Township 21		NMPM	CountyEDDY
Pit or Below-grade Tank Application	3196.2' GL	hether DR, RKB, RT, C	R, etc.)	
	aterDistance from ne	earest fresh water well	Distance from neare	st surface water
Pit Liner Thickness: mil	Below-Grade Tank: Vo	olumeb	bls; Construction Mate	rial
12. Check	Appropriate Box to Ir	ndicate Nature of N	otice, Report or O	ther Data
NOTICE OF IN	ITENTION TO:		SUBSEQUENT	DEDODT OF
PERFORM REMEDIAL WORK	PLUG AND ABANDON	N 🗌   REMEDIAL		☐ ALTERING CASING ☐
TT14D0D4DU1/4D41/D01/	CHANGE PLANS	COMMEN	CE DRILLING OPNS.	
TEMPORARILY ABANDON	CHANGE FLANS			
PULL OR ALTER CASING	MULTIPLE COMPL	I		
		☐ CASING/C		
OTHER:  13. Describe proposed or compof starting any proposed w	MULTIPLE COMPL  oleted operations. (Clearl	CASING/C  OTHER:M ly state all pertinent deta	EMENT JOB  ECHANICAL INTER  Ails, and give pertiner	
OTHER:  13. Describe proposed or compof starting any proposed wor recompletion.	MULTIPLE COMPL  oleted operations. (Clearl  ork). SEE RULE 1103.	CASING/C  OTHER:M ly state all pertinent deta For Multiple Completic	EMENT JOB  ECHANICAL INTER  The partiner  Th	RGRITY TEST X at dates, including estimated date diagram of proposed completion
OTHER:  13. Describe proposed or compof starting any proposed w	MULTIPLE COMPL  oleted operations. (Clearl ork). SEE RULE 1103. 15  bbls 2% KCI FW down	CASING/C  OTHER:M ly state all pertinent deta For Multiple Completion 2-3/8" x 5-1/2" annulu	EMENT JOB  ECHANICAL INTER  Ails, and give pertiner  airs: Attach wellbore  s. Casing on hard vac	RGRITY TEST X at dates, including estimated date diagram of proposed completion
OTHER:  13. Describe proposed or compof starting any proposed wor recompletion.  Perform MIT test 1/12/05. pump 6	MULTIPLE COMPL  oleted operations. (Clearl ork). SEE RULE 1103. 15  bbls 2% KCI FW down	CASING/C  OTHER:M ly state all pertinent deta For Multiple Completion 2-3/8" x 5-1/2" annulu	EMENT JOB  ECHANICAL INTER  Ails, and give pertiner  airs: Attach wellbore  s. Casing on hard vac	RGRITY TEST X at dates, including estimated date diagram of proposed completion
OTHER:  13. Describe proposed or compof starting any proposed wor recompletion.  Perform MIT test 1/12/05. pump 6	MULTIPLE COMPL  oleted operations. (Clearl ork). SEE RULE 1103. 15  bbls 2% KCI FW down	CASING/C  OTHER:M ly state all pertinent deta For Multiple Completion 2-3/8" x 5-1/2" annulu	EMENT JOB  ECHANICAL INTER  Ails, and give pertiner  airs: Attach wellbore  s. Casing on hard vac	RGRITY TEST X at dates, including estimated date diagram of proposed completion
OTHER:  13. Describe proposed or compof starting any proposed wor recompletion.  Perform MIT test 1/12/05. pump 6	MULTIPLE COMPL  oleted operations. (Clearl ork). SEE RULE 1103. 15  bbls 2% KCI FW down	CASING/C  OTHER:M ly state all pertinent deta For Multiple Completion 2-3/8" x 5-1/2" annulu	EMENT JOB  ECHANICAL INTER  Ails, and give pertiner  Ins: Attach wellbore  S. Casing on hard vac	RGRITY TEST X at dates, including estimated date diagram of proposed completion
OTHER:  13. Describe proposed or compof starting any proposed wor recompletion.  Perform MIT test 1/12/05. pump 6	MULTIPLE COMPL  oleted operations. (Clearl ork). SEE RULE 1103. 15  bbls 2% KCI FW down	CASING/C  OTHER:M ly state all pertinent deta For Multiple Completion 2-3/8" x 5-1/2" annulu	EMENT JOB  ECHANICAL INTER  Ails, and give pertiner  Ins: Attach wellbore  S. Casing on hard vac	RGRITY TEST X at dates, including estimated date diagram of proposed completion
OTHER:  13. Describe proposed or compof starting any proposed wor recompletion.  Perform MIT test 1/12/05. pump 6	MULTIPLE COMPL  oleted operations. (Clearl ork). SEE RULE 1103. 15  bbls 2% KCI FW down	CASING/C  OTHER:M ly state all pertinent deta For Multiple Completion 2-3/8" x 5-1/2" annulu	EMENT JOB  ECHANICAL INTER  Ails, and give pertiner  Ins: Attach wellbore  S. Casing on hard vac	RGRITY TEST X at dates, including estimated date diagram of proposed completion
OTHER:  13. Describe proposed or compof starting any proposed wor recompletion.  Perform MIT test 1/12/05. pump 6	MULTIPLE COMPL  oleted operations. (Clearl ork). SEE RULE 1103. 15  bbls 2% KCI FW down	CASING/C  OTHER:M ly state all pertinent deta For Multiple Completion 2-3/8" x 5-1/2" annulu	EMENT JOB  ECHANICAL INTER  Ails, and give pertiner  Ins: Attach wellbore  S. Casing on hard vac	RGRITY TEST X at dates, including estimated date diagram of proposed completion
OTHER:  13. Describe proposed or compof starting any proposed wor recompletion.  Perform MIT test 1/12/05. pump 6	MULTIPLE COMPL  oleted operations. (Clearl ork). SEE RULE 1103. 15  bbls 2% KCI FW down	CASING/C  OTHER:M ly state all pertinent deta For Multiple Completion 2-3/8" x 5-1/2" annulu	EMENT JOB  ECHANICAL INTER  Ails, and give pertiner  Ins: Attach wellbore  S. Casing on hard vac	RGRITY TEST X at dates, including estimated date diagram of proposed completion
OTHER:  13. Describe proposed or compof starting any proposed wor recompletion.  Perform MIT test 1/12/05. pump 6	MULTIPLE COMPL  oleted operations. (Clearl ork). SEE RULE 1103. 1  bbls 2% KCI FW down at 1/10/05 but no OCD wi	CASING/C  OTHER:M ly state all pertinent deta For Multiple Completion 2-3/8" x 5-1/2" annulu	EMENT JOB  ECHANICAL INTER  Ails, and give pertiner  Ins: Attach wellbore  S. Casing on hard vac	RGRITY TEST X at dates, including estimated date diagram of proposed completion
OTHER:  13. Describe proposed or compostarting any proposed wor recompletion.  Perform MIT test 1/12/05. pump 6 NMOCD in Artesia informed of testing and the second	MULTIPLE COMPL  oleted operations. (Clearl ork). SEE RULE 1103. 1  bbls 2% KCI FW down at 1/10/05 but no OCD wi	CASING/C  OTHER:M ly state all pertinent deta For Multiple Completion 2-3/8" x 5-1/2" annulu	EMENT JOB  ECHANICAL INTER  Ails, and give pertiner  Ins: Attach wellbore  S. Casing on hard vac	RGRITY TEST X at dates, including estimated date diagram of proposed completion
OTHER:  13. Describe proposed or compostarting any proposed wor recompletion.  Perform MIT test 1/12/05. pump 6 NMOCD in Artesia informed of test	MULTIPLE COMPL  oleted operations. (Clearl ork). SEE RULE 1103. 1  bbls 2% KCI FW down at 1/10/05 but no OCD wi	CASING/C  OTHER:M ly state all pertinent deta For Multiple Completion 2-3/8" x 5-1/2" annulu	EMENT JOB  ECHANICAL INTER  Ails, and give pertiner  Ins: Attach wellbore  S. Casing on hard vac	RGRITY TEST X at dates, including estimated date diagram of proposed completion
OTHER:  13. Describe proposed or compostarting any proposed wor recompletion.  Perform MIT test 1/12/05. pump 6 NMOCD in Artesia informed of testing and the second	MULTIPLE COMPL  oleted operations. (Clearl ork). SEE RULE 1103. 1  bbls 2% KCI FW down at 1/10/05 but no OCD wi	CASING/C  OTHER:M ly state all pertinent deta For Multiple Completion 2-3/8" x 5-1/2" annulu	EMENT JOB  ECHANICAL INTER  Ails, and give pertiner  Ins: Attach wellbore  S. Casing on hard vac	RGRITY TEST X at dates, including estimated date diagram of proposed completion
OTHER:  13. Describe proposed or compostarting any proposed wor recompletion.  Perform MIT test 1/12/05. pump 6 NMOCD in Artesia informed of test on or before  This well must be in physical of the second or before.	MULTIPLE COMPL  oleted operations. (Clearl ork). SEE RULE 1103. 15  bbls 2% KCI FW down st 1/10/05 but no OCD wi  ompliance  above is true and comple	CASING/C  OTHER:M  ly state all pertinent deta  For Multiple Completion  2-3/8" x 5-1/2" annulu  itness. MIT test was unserted to the best of my known.	EMENT JOB  ECHANICAL INTER  iils, and give pertiner  ns: Attach wellbore  s. Casing on hard vac  successful.	RGRITY TEST  It dates, including estimated date diagram of proposed completion uum. Mike Bratcher with
OTHER:  13. Describe proposed or compostarting any proposed wor recompletion.  Perform MIT test 1/12/05. pump 6 NMOCD in Artesia informed of test	MULTIPLE COMPL  oleted operations. (Clearl ork). SEE RULE 1103. 15  bbls 2% KCI FW down st 1/10/05 but no OCD wi  ompliance  above is true and comple	CASING/C  OTHER:M  ly state all pertinent deta  For Multiple Completion  2-3/8" x 5-1/2" annulu  itness. MIT test was unserted to the best of my known.	EMENT JOB  ECHANICAL INTER  iils, and give pertiner  ns: Attach wellbore  s. Casing on hard vac  successful.	RGRITY TEST  It dates, including estimated date diagram of proposed completion uum. Mike Bratcher with
OTHER:  13. Describe proposed or compostarting any proposed wor recompletion.  Perform MIT test 1/12/05. pump 6 NMOCD in Artesia informed of test on or before  This well must be in physical of the second or before.	MULTIPLE COMPL  oleted operations. (Clearl ork). SEE RULE 1103.  bbls 2% KCI FW down st 1/10/05 but no OCD wi  ompliance  above is true and comple closed according to NMOCD	CASING/C  OTHER:M  ly state all pertinent deta  For Multiple Completion  2-3/8" x 5-1/2" annulu  itness. MIT test was unserted to the best of my known.	EMENT JOB  ECHANICAL INTER  inils, and give pertiner  ns: Attach wellbore  s. Casing on hard vac  successful.   owledge and belief. I  rmit or an (attached)	RGRITY TEST  It dates, including estimated date diagram of proposed completion uum. Mike Bratcher with
OTHER:  13. Describe proposed or compostarting any proposed wor recompletion.  Perform MIT test 1/12/05. pump 6 NMOCD in Artesia informed of test on or before  This well must be in physical of the physical	MULTIPLE COMPL  oleted operations. (Clearl ork). SEE RULE 1103. 15  bbls 2% KCI FW down at 1/10/05 but no OCD with the complete of the closed according to NMOCD  above is true and complete closed according to NMOCD	CASING/C  OTHER:M  ly state all pertinent deta  For Multiple Completion  2-3/8" x 5-1/2" annulu  itness. MIT test was unsulu  ete to the best of my known and guidelines [], a general per	EMENT JOB  ECHANICAL INTER  Ails, and give pertiner  Ins: Attach wellbore  Is. Casing on hard vacuccessful.   Divided and belief. I  Trmit or an (attached)  k	RGRITY TEST  It dates, including estimated date diagram of proposed completion uum. Mike Bratcher with  Summary of the completion of the c
OTHER:  13. Describe proposed or compostarting any proposed wor recompletion.  Perform MIT test 1/12/05. pump 6 NMOCD in Artesia informed of test on or before  This well must be in physical of the physical	MULTIPLE COMPL  oleted operations. (Clearl ork). SEE RULE 1103. 15  bbls 2% KCI FW down at 1/10/05 but no OCD with the complete of the closed according to NMOCD  above is true and complete closed according to NMOCD	CASING/C  OTHER:M  ly state all pertinent deta  For Multiple Completion  2-3/8" x 5-1/2" annulu  itness. MIT test was uns  ete to the best of my known guidelines [], a general per  TITLE Production Clere	EMENT JOB  ECHANICAL INTER  Ails, and give pertiner  Ins: Attach wellbore  Is. Casing on hard vacuccessful.   Divided and belief. I  Trmit or an (attached)  k	RGRITY TEST  It dates, including estimated date diagram of proposed completion uum. Mike Bratcher with  Summarized that any pit or belowalternative OCD-approved plan .  DATE 01/20/2005