

RECEIVED

NOV 10 2003

State of New Mexico

Submit 3 Copies
to Appropriate
District Office

OCD-ARTESIA

Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-03

DISTRICT I
P.O. Box 1940, Hobbs, NM 88240

DISTRICT II
P.O. Drawer 00, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Artesia, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-62894	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. VA-2401	
7. Lease Name or Unit Agreement Name Louise Yates	
8. Well No. 1	
9. Pool name or Wildcat Wolf-Lake San Andres, South	

SUNDARY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Jalapeno Corporation	
3. Address of Operator P.O. Box 1608, Albuquerque, NM 87103-1608	
4. Well Location Unit Letter <u>N</u> : <u>330</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>7</u> Township <u>9S</u> Range <u>28E</u> NMPM <u>Chaves</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/24/03 Spot 25 sx "C" cmt. from 2366' to 2119' WOC.
 10/27/03 Tag TOC @ 2103', circ. hole w/ 9.5# mud.
 10/27/03 Cut and pull 5-1/2" csg. @ 1219'.
 10/27/03 Spot 35 sx "C" cmt. @ 1295', WOC & tag TOC @ 1117'.
 10/27/03 Spot 35 sx "C" cmt. @ 463' WOC.
 10/28/03 Tag TOC @ 326'.
 10/28/03 Spot 25 sx "C" cmt. from 60' to surface WOC & tag TOC @ surface.
 10/29/03 RDMO. Cut off wellhead, install dry hole marker, & clean location.
 11/5/03

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Randall Minear TITLE Agent DATE 10-31-03
 TYPE OR PRINT NAME Randall Minear Thompson President 11/6/03 TELEPHONE NO. 432-530-0907

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep DATE FEB 28 2005
 CONDITIONS OF APPROVAL, IF ANY:



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Lori Wrotenberg

Director

Oil Conservation Division

10 November 2003

Jalapeno Corporation

P. O. Box 1608

Albuquerque, New Mexico 87103-1608

Form C-103 Report of Plugging for your Louise Yates # 1 N-7-9-28 API 30-005-62894

Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- OK To Release
2/28/05
[Signature]*
- ☒ 1. All pits have been filled and leveled.
 - ☒ 2. Rat hole and cellar have been filled and leveled.
 - ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
 - ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment. *See letter*
 - ☒ 5. The dead men and tie downs have been cut and removed.
 - ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
 - ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

[Signature]
Name
[Signature]
Title

[Signature]
Van Barton
Field Rep. II

FILE COPY