

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

OCD Rec'd: 08/27/18

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	OXY USA INC	Contact	WADE DITTRICH	
Address	1017 W. Stanolind, Hobbs, NM 88240	Telephone No.	575-390-2828	
Facility Name	CEDAR CANYON 29 FEDERAL COM #3H	Facility Type	OIL WELL	
Surface Owner	Mineral Owner	FEDERAL	API No.	30-015-42993

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	29	24S	29E	1990	NORTH	210	EAST	EDDY

Latitude__32.190250__ Longitude__-103.9986__ NAD83

NATURE OF RELEASE

Type of Release	OIL & PRODUCED WATER	Volume of Release	8 bbls OIL & 2 bbls PRODUCED WATER	Volume Recovered	0 bbls
Source of Release	4 inch poly line failure	Date and Hour of Occurrence	08/05/2017	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	MIKE BRATCHER-NMOCD; MARIA PRUITT-NMOCD; SHELLY TUCKER-BLM		
By Whom?	WADE DITTRICH	Date and Hour	08/07/2017 @ 11:38 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Spill occurred due to a 4 inch poly line failure. Line has been repaired and put back in service.

Describe Area Affected and Cleanup Action Taken.*

The impacted area is approximately 25x100 FT, Leak did leave the location-leak is behind the Cedar Canyon 28 4 CTB (measurements are subject to change with GPS tracking). Remediation will be completed in accordance with a remediation plan approved by the NMOCD and BLM. REMEDIATION COMPLETED; NMOCD 2RP-4339

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: WADE DITTRICH	Approved by Environmental Specialist: 		
Title: ENVIROMENTAL COORDINATOR	Approval Date: 08/28/18	Expiration Date: N/A	
E-mail Address: wade.dittrich@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 8/27/2018	Phone: 575-390-2828	Like Approval BLM	

* Attach Additional Sheets If Necessary

FINAL 2RP-4339