District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Responsible Party

EOG Y Resources, Inc.

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAB1834454137
District RP	2RP-5094
Facility ID	
Application ID	pAB1834453495

Release Notification

Responsible Party

OGRID

25575

Chase Settle 575-748-417] Contact mail Incident # (assigned by OCI) Contact mailing address 104 S. 4th Location of Release Source Latitude 32.6705933	Contact Name				Contact Telephone				
Location of Release Source					575-748-4171				
Location of Release Source Latitude 32.6705933						Incident # (assigned by OCD)			
Location of Release Source Latitude 32.6705933 Longitude -104.5177307 (NAD 83 in decimal degrees to 5 decimal places) Site Name Roy #3 SWD Date Release Discovered 11/13/18 API# 30-015-26562 Unit Letter Section Township Range County P 7 19S 25E Eddy Surface Owner: State Federal Tribal Private (Name:			es.com						
Location of Release Source Latitude 32.6705933		ing address							
Latitude 32.670.5933	104 S. 4 th								
Site Name Roy #3 SWD Date Release Discovered 11/13/18 API# 30-015-26562 Unit Letter Section Township Range County P 7 198 25E Eddy Surface Owner: State Federal Tribal Private (Name: Nature and Volume of Release Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below) Crude Oil Volume Released (bbls) Volume Recovered (bbls) Produced Water Volume Released (bbls) 190 Volume Recovered (bbls) 120 Is the concentration of dissolved chloride in the produced water >10,000 mg/1? Condensate Volume Released (bbls) Volume Recovered (bbls) Natural Gas Volume Released (Mcf) Volume Recovered (Mcf) Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units) Cause of Release Coupling between 2 pvc nipples failed on the line between gun barrel and produced water tank.	Location of Release Source								
Site Name Roy #3 SWD Date Release Discovered 11/13/18 API# 30-015-26562 Unit Letter Section Township Range County P 7 19S 25E Eddy Surface Owner: State Federal Tribal Private (Name: Nature and Volume of Release Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below) Crude Oil Volume Released (bbls) Volume Recovered (bbls) Produced Water Volume Released (bbls) 190 Volume Recovered (bbls) 120 Is the concentration of dissolved chloride in the produced water >10,000 mg/1? Condensate Volume Released (bbls) Volume Recovered (bbls) Natural Gas Volume Released (Mcf) Volume Recovered (Mcf) Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units) Cause of Release Coupling between 2 pvc nipples failed on the line between gun barrel and produced water tank.									
Date Release Discovered 11/13/18 API# 30-015-26562									
Unit Letter Section Township Range County P 7 19S 25E Eddy Surface Owner: State Federal Tribal Private (Name:						Site Type			
P 7 198 25E Eddy Surface Owner: State Federal Tribal Private (Name:	Date Release	Discovered	11/13/18			API# 30-015-26562			
P 7 198 25E Eddy Surface Owner: State Federal Tribal Private (Name:	Unit Letter	Section	Township	Range		Coun	ntv]	
Nature and Volume of Release Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below) Crude Oil Volume Released (bbls) Volume Recovered (bbls) Produced Water Volume Released (bbls) 190 Volume Recovered (bbls) 120 Is the concentration of dissolved chloride in the produced water >10,000 mg/l? Condensate Volume Released (bbls) Volume Recovered (bbls) Natural Gas Volume Released (Mcf) Volume Recovered (Mcf) Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units) Cause of Release Coupling between 2 pvc nipples failed on the line between gun barrel and produced water tank.									
Nature and Volume of Release Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below) Crude Oil Volume Released (bbls) Volume Recovered (bbls) Produced Water Volume Released (bbls) 190 Volume Recovered (bbls) 120 Is the concentration of dissolved chloride in the produced water >10,000 mg/l? Condensate Volume Released (bbls) Volume Recovered (bbls) Natural Gas Volume Released (Mcf) Volume Recovered (Mcf) Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units) Cause of Release Coupling between 2 pvc nipples failed on the line between gun barrel and produced water tank.				" 1 \(\frac{1}{2}\) \(\frac{1}2\) \(\frac{1}2\	r			,	
Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below) □ Crude Oil Volume Released (bbls) Volume Recovered (bbls) □ Produced Water Volume Released (bbls) 190 Volume Recovered (bbls) 120 □ Is the concentration of dissolved chloride in the produced water >10,000 mg/l? □ Condensate Volume Released (bbls) Volume Recovered (bbls) □ Natural Gas Volume Released (Mcf) Volume Recovered (Mcf) □ Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units) Cause of Release Coupling between 2 pvc nipples failed on the line between gun barrel and produced water tank.	Surface Owner	r: State	Federal Tr	ibal 🔀 Private (A	Vame:)	
Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below) □ Crude Oil Volume Released (bbls) Volume Recovered (bbls) □ Produced Water Volume Released (bbls) 190 Volume Recovered (bbls) 120 □ Is the concentration of dissolved chloride in the produced water >10,000 mg/l? □ Condensate Volume Released (bbls) Volume Recovered (bbls) □ Natural Gas Volume Released (Mcf) Volume Recovered (Mcf) □ Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units) Cause of Release Coupling between 2 pvc nipples failed on the line between gun barrel and produced water tank.				NT - 4	. T 7. I		7 - 1		
☐ Crude Oil Volume Released (bbls) Volume Recovered (bbls) ☐ Produced Water Volume Released (bbls) 190 Volume Recovered (bbls) 120 ☐ Is the concentration of dissolved chloride in the produced water >10,000 mg/l? ☐ Yes ☐ No ☐ Condensate Volume Released (bbls) Volume Recovered (bbls) ☐ Natural Gas Volume Released (Mcf) Volume Recovered (Mcf) ☐ Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units) Cause of Release Coupling between 2 pvc nipples failed on the line between gun barrel and produced water tank.				Nature and	l V OI	ume of 1	Kelease		
☐ Crude Oil Volume Released (bbls) Volume Recovered (bbls) ☐ Produced Water Volume Released (bbls) 190 Volume Recovered (bbls) 120 ☐ Is the concentration of dissolved chloride in the produced water >10,000 mg/l? ☐ Yes ☐ No ☐ Condensate Volume Released (bbls) Volume Recovered (bbls) ☐ Natural Gas Volume Released (Mcf) Volume Recovered (Mcf) ☐ Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units) Cause of Release Coupling between 2 pvc nipples failed on the line between gun barrel and produced water tank.		Motoriol	(c) Delegged (Salact of	I that annly and attach	coloulat	ions or specific	instification for the	a volumes provided helow)	
Is the concentration of dissolved chloride in the produced water >10,000 mg/l? Condensate Volume Released (bbls) Volume Recovered (bbls) Natural Gas Volume Released (Mcf) Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units) Cause of Release Coupling between 2 pvc nipples failed on the line between gun barrel and produced water tank.				ions of specific					
produced water >10,000 mg/l? Condensate Volume Released (bbls) Volume Recovered (bbls) Volume Recovered (Mcf) Other (describe) Volume/Weight Released (provide units) Cause of Release Coupling between 2 pvc nipples failed on the line between gun barrel and produced water tank.	Produced	Water	Volume Released (bbls) 190				Volume Recovered (bbls) 120		
☐ Condensate Volume Released (bbls) Volume Recovered (bbls) ☐ Natural Gas Volume Released (Mcf) Volume Recovered (Mcf) ☐ Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units) Cause of Release Coupling between 2 pvc nipples failed on the line between gun barrel and produced water tank.			l I			in the	⊠ Yes □ No		
Other (describe) Volume/Weight Released (provide units) Volume/Weight Recovered (provide units) Cause of Release Coupling between 2 pvc nipples failed on the line between gun barrel and produced water tank.	Condensa	te					Volume Recovered (bbls)		
Cause of Release Coupling between 2 pvc nipples failed on the line between gun barrel and produced water tank.	□ Natural Gas Volume Released (Mcf)					Volume Recovered (Mcf)			
Coupling between 2 pvc nipples failed on the line between gun barrel and produced water tank.	Other (describe) Volume/Weight Released (provide units)			, I	Volume/Weig	ght Recovered (provide units)			
Coupling between 2 pvc nipples failed on the line between gun barrel and produced water tank.									
	Cause of Rele	ease							
	Coupling bety	ween 2 pvc r	nipples failed on th	ne line between gu	n barr	el and produ	ced water tank.		

Form C-141 Page 2

State of New Mexico Oil Conservation Division

Incident ID	NAB1834454137
District RP	2RP-5094
Facility ID	
Application ID	pAB1834453495

Was this a major release as defined by	If YES, for what reason(s) does the responsible	party consider this a major release? **		
19.15.29.7(A) NMAC?				
Yes □ No				
	** Operator failed to supply the answer to this question	n regarding the major release: $^{\mathcal{AB}}$		
If YES, was immediate no	notice given to the OCD? By whom? To whom?			
** Operator failed to sup	pply the answer to these questions. AB			
	Initial Respo	nse		
The responsible p	party must undertake the following actions immediately unless	s they could create a safety hazard that would result in injury		
☐ The source of the rele	ease has been stopped.			
	as been secured to protect human health and the en	vironment.		
Released materials ha	ave been contained via the use of berms or dikes, a	absorbent pads, or other containment devices.		
All free liquids and re	recoverable materials have been removed and man	aged appropriately.		
If all the actions described	ed above have <u>not</u> been undertaken, explain why:	-		
		,		
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.				
		my knowledge and understand that pursuant to OCD rules and		
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.				
Printed Name: Chase Settle	le Title: Rep Safety & Environn	nental II		
Signature:	Da	te: <u>//-28-/8</u>		
email: chase_settle@eogr	resources.com Te	elephone: <u>575-748-4171</u>		
OCD Only				
Received by:	ntamente Date	: _12/10/2018		