District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410

State of New Mexico Energy Minerals and Natural Resources

OCT 07 2011

RECEIVED

Form C-141 Revised October 10, 2003

NMOCD ARTESIAND Office in accordance with Rule 116 on back side of form

Oil Conservation Division 1220 South St. Francis Dr.

District IV	1220	1220 South St. Francis Dr.			with Rule 116 on back								
1220 S. St. Francis Dr., Santa Fc, NM 87505 Santa					ınta F	Fe, NM 87505						side of form	
<u> </u>			Rel	ease Notific	catio	n and C	orrective A	ction					
nKNWII	109138	665				OPERA'	TOR	7	☐ Initi	ial Report	\boxtimes	Final Repor	
Name of Co		Contact Natalie Gladden											
Name of Company Apache Corp. Address P.O. Box 1849, Eunice, NM, 88231						Telephone No. (575) 390-4186							
Facility Na		Facility Type SWD											
EAUC50)													
Surface Ou	mor RIM	OCD			Lease ?	No. 30-015	03184						
												· · · · · · · · · · · · · · · · · · ·	
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County													
Unit Letter	Section	Township	Range	Feet from the	North	/South Line	Feet from the	East/W	est Line	County			
K	29	178	29E	2310'	FSL		1650'	FWL		Eddy			
Latitude Longitude													
NATURE OF RELEASE													
Type of Release Produced Water							Release 525			Recovered 5	00		
Source of Release Automation Failure							am Wham?	L	07/15/11	1030am			
Was Immediate Notice Given?							If YES, To Whom? Randy Dade						
By Whom?							Date and Hour 03/29/11 @ 3:11pm						
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.						
☐ Yes ☒ No													
If a Watercou	rse was Im	pacted, Descri	be Fully.	,		.l				***********			
	•		•				•						
Describe Cau	se of Proble	m and Deme	tial Action	Taken *									
Describe Cause of Problem and Remedial Action Taken.* Automation failure caused tanks to overflow. Standing fluid was vacuumed up immediately and soil was pushed up towards metal berms to keep fluid													
from exiting t				J		•	•	•	•			•	
Describe Area	a Affected a	nd Cleanun A	ction Tak	en.‡									
				reas of the contair	ıment fl	loor. The imp	acted area was ex	cavated	to 10 in. to	o 1.5 ft. belo	w grou	nd surface,	
				o a NMOCD appro									
				d then plugged. S									
backfilled wit			it below g	round surface, and	i no wa	ter was detect	ed. The temporar	ry well w	as plugge	d, and the ex	cavano	n was	
Dackinica Wit	ii Cican Can	CHG.											
				is true and comple									
				d/or file certain re									
				c of a C-141 repor investigate and re									
				ance of a C-141 n									
federal, state,								Фъроцию	LILY 101 00	mpnumo w			
	$\overline{}$		\sim 1			OIL CONSERVATION DIVISION							
Signature:	nr												
Oignutire.j_	<u> </u>	$\frac{m}{c}$				Approved by District Supervisor:							
Printed Name:	Natalie Gl	adden		Approved by District Supervisor.									
						OCT 0 7 2011							
Title: EH&S Environmental Tech						Approval Date: U / ZUII Expiration Date: NA							
E-mail Address: Natalie eladden@anachecoro.com						Conditions of	Annroval: NA	/	γ				

Phone: (575) 390-4186 * Attach Additional Sheets If Necessary

Attached | Attached | Altached |