District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resource

NOV 4 2011

Form C-141 tevised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 NMOCD ARTESTATE Copies to appropriate Copies to appropriate of Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nMLBI131	137545	t William	ALCIN	ase intille	**************************************	OPERA'	A ST A WOLL OF THE STATE OF THE	4.65	☑ Initia	ıl Report	\boxtimes	Final Report	
Name of Company. COG OPERATING LLC 429/37 Contact: Pat Ellis													
Address	550 W.	Texas, Suite	100, Mi	dland, TX 7970	Telephone No. 432-230-0077								
Facility Name GJ West Coop #210 Tank Battery Facility Type Tank Battery													
Surface Oursign Strike W Ministral Oursign Strike W A DAM 20 015 20702													
Surface Owner State Mineral Owner Lease No. (API#) 30-015-36703												3-30/03	
1 2013	LOCATION OF RELEASE												
Unit Letter C	Section 16	Township 17S	Range 29E	Feet from the	North/	South Line	Feet from the	East/W	est Line	County	ddy		
Latitude 32 50.334 Longitude 104 04.981													
- NATURE OF RELEASE													
Type of Release Oil							Release 20bbls						
Source of Re	lease Oil ta	nk	, , , ,	na na piangan pan			lour of Occurrent			Hour of Disc			
10/19/2011 8:00 a.m. 10/19/2011 8:00 a.m. Was Immediate Notice Given?													
Was Immediate Notice Given? ☐ Yes ☒ No ☒ Not Required ☐ If YES, To Whom?													
By Whom?		Date and I	lour			14 <u>(\$ 1</u>	<i>-</i> 11, -						
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.						
☐ Yes ☒ No													
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.*													
500 mili amp fuse blew on the lact causing the oil tank to overflow. The fuse has been replaced.													
Describe Area Affected and Cleanup Action Taken.*													
Initially 20bbls of oil were released from the oil tank and we were able to recover 19bbls with a vacuum truck. All of the fluid was completely contained inside the berm walls of the facility. This facility is lined with a 40mil plastic liner. All of the standing fluid has been picked up, the liner has been steamed, and the contaminated gravel has been removed. Clean gravel has been added to the facility. The tank battery has been returned to its prior condition.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
Signature:							OIL CONSERVATION DIVISION						
Printed Name		Josh	A	Approved by District Supervisor:									
Title:		Approval DaNOV 0 7 2011 Expiration Date: NA											
E-mail Addre	ss:	jrusso@conch	oresource	s.com	c	onditions of	Approval: N/	• \ /) ,	Attached			
Date: 11/02	2/2011	Pho	ne: 4	12-212-2399	ļ		(-t	rnul		ļ			

* Attach Additional Sheets If Necessary

2RP-951